

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003288/KVY3E2

Date: 10/06/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00085342100		
Claimant Vehicle No :	SKX7480U	Insured Vehicle No :	GBH5885P		
Date of Loss:	06/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202359/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX7480U	Engine No:	FA20A811967
Make & Model:	SUBARU FORESTER, 2.0 XT CVT AWD SR (A)	Chassis No:	JF1SJGK85FG061005
Reg. Date:	28/12/2015 (Man. Year: 2015)	Odometer:	88911 km
Colour:	Metallic Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,056.32	1,206.40	849.92	41.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	920.00	440.00	32.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,416.32	2,126.40	1,289.92	37.76
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	3,416.32	1,700.00	1,716.32	50.24
+ GST 7.00/7.00% (\$\$)	239.14	119.00	120.14	50.24
Nett Amount (\$\$)	3,655.46	1,819.00	1,836.46	50.24

INSPECTION

Date of Assignment:	11/04/2022	
Date Inspected:	12/04/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX7480U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	300.70 FL	*300.70 FL
2	1		*FRONT FENDER LOWER GARNISH LH (NPA)	Serviceable	0.00 FL	*- FL
3	1		*FRONT FENDER BRACKET REAR LH	Repair	18.90 FL	*- FL
4	1		*FRONT FENDER COWLING LH	Cracked	96.30 FL	*96.30 FL
5	8		*FRONT FENDER COWLING CLIPS	Necessary	42.40 FL	*42.40 FL
6	1		*FRONT DOOR LH	Bent	720.40 FL	*720.40 FL
7	1		*FRONT DOOR TAPE FRONT LH	Necessary	8.30 FL	*8.30 FL
8	1		*FRONT DOOR TAPE TOP LH	Necessary	24.30 FL	*24.30 FL
9	1		*FRONT DOOR TAPE REAR LH	Necessary	24.90 FL	*24.90 FL
10	1		*FRONT DOOR LOWER GARNISH WITH GARNISH CHROME MOULDING LH	Dented / Cut	290.70 FL	*290.70 FL
11	1		*FRONT DOOR RUBBER @DOOR LH	Serviceable	94.20 FL	*- FL
12	1		*FRONT DOOR RUBBER @DOOR BOTTOM LH	Serviceable	19.40 FL	*- FL
13	1		*FRONT DOOR HINGE LOWER LH	Repair	48.10 FL	*- FL
14	1		*FRONT DOOR CHECK LH	Serviceable	60.50 FL	*- FL
15	1		*FRONT DOOR WINDOW REGULATOR WITH MOTOR LH	Serviceable	300.20 FL	*- FL
16	1		*FRONT DOOR LOCK LH	Repair	280.40 FL	*- FL
17	1		*FRONT WHEEL HUB WITH BEARING LH	Not Necessary	240.70 FL	*- FL
18	1		*TYRE LHF (NPA)	Serviceable	0.00 FS	*- FS
19	1		*SPORT RIM LHF (NPA)	Serviceable	0.00 FS	*- FS
Sub Total (S\$)						2,570.40 1,508.00
- List Item Discount on L Items 20.00/20.00% (S\$)						514.08 301.60
Total Parts (S\$)						2,056.32 1,206.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
2	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR / FACILITATE REPAIR	New	120.00	60.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	60.00
4	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR FRONT FENDER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
5	TO SPRAY FRONT FENDER LH, FRONT DOOR LH	New	500.00	400.00
Gross Labour Cost (\$\$)			1,360.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >