

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6765X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	CUT	1,510.00	1,510.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,150.00	-
1	REAR BUMPER BRACKET RH	SERVICEABLE	125.00	-
1	REAR BUMPER BRACKET LH	SERVICEABLE	125.00	-
1	REAR BUMPER LOWER COVER	SERVICEABLE	325.00	-
2	REAR BUMPER LOWER BRACKET LH/RH @\$135.00	SERVICEABLE	270.00	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	175.00	-
	LESS 20% DISCOUNT		-736.00	-302.00
			2,944.00	1,208.00
	NETT ITEMS			
1	REAR BUMPER RUBBER MAT (N)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (N)	DENTED	388.00	388.00
	LESS 10% DISCOUNT		-	-43.80
			438.00	394.20
	<u>LABOUR</u>			
	PANEL BEATING.		900.00	400.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,340.00	710.00
	GRAND TOTAL		4,722.00	2,312.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,850.00

Report Ref No. NS/INC22003297/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser