

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2484M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CUT	481.10	481.10
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER UPPER MOULDING	SCRATCHED	368.50	368.50
1	FRT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRT FENDER BLUEDRIVE RH	NECESSARY	26.60	26.60
1	FRT WHEEL CAP RH	SCRATCHED	346.40	346.40
1	HEADLAMP RH	SCRATCHED	2,110.30	2,110.30
1	DAYLIGHT RH	SERVICEABLE	642.50	-
1	DAYLIGHT GRILLE RH	SERVICEABLE	93.45	-
	LESS 20% DISCOUNT		-935.93	-670.98
			3,743.72	2,683.92
	<u>LABOUR</u>			
	TOWING FEE (NPA).		-	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		800.00	700.00
	SPRAY PAINTING.		600.00	500.00
	CHECK WIRINGS.		40.00	20.00
	TOFF KOTE.		40.00	20.00
			1,480.00	1,240.00
	GRAND TOTAL		5,223.72	3,923.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,150.00

Report Ref No. NS/INC22003299/Vtcn2



THEVAN THOMAS KARTHIKESAVAN

(CONFIRMED)



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**