

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22003303/RQY3E2**Date:** 23/12/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001932024
<b>Claimant Vehicle No :</b>	SMX9567S	<b>Insured Vehicle No :</b>	FBD7989G
Date of Loss:	07/04/2022	Nature of Claim:	TP
		Claim No:	272446

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMX9567S</b>	Engine No:	G4FGGU259682
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU290673
Reg. Date:	01/12/2016 (Man. Year: 2016)	Odometer:	80901 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,932.60	802.32	4,130.28	83.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	690.00	1,100.00	61.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,722.60</b>	<b>1,492.32</b>	<b>5,230.28</b>	<b>77.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	470.58	104.46	366.12	77.80
<b>Nett Amount (S\$)</b>	<b>7,193.18</b>	<b>1,596.78</b>	<b>5,596.40</b>	<b>77.80</b>

INSPECTION

Date of Assignment:	23/12/2022	
Date Inspected:	13/04/2022	Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMX9567S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	595.40 FL	*595.40 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	45.00 FL	*- FL
3	1		*REAR BUMPER BRACKET LH	Not Necessary	55.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	35.00 FL	*- FL
5	1		*REAR BUMPER LOWER SKIRT	Cracked	370.00 FL	*370.00 FL
6	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	440.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	395.00 FL	*- FL
8	1		*REAR FENDER RH	Not Necessary	1,768.30 FL	*- FL
9	1		*REAR TAILLAMP RH	Not Necessary	763.80 FL	*- FL
10	1		*REAR TAILLAMP LOWER BRACKET LH	Not Necessary	55.00 FL	*- FL
11	1		*REAR TAILLAMP LOWER PANEL LH	Not Necessary	372.00 FL	*- FL
12	1		*REAR EXHAUST PIPE	Not Necessary	1,140.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,139.50</b>	<b>995.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,206.90	193.08
<b>Total Parts (\$\$)</b>	<b>4,932.60</b>	<b>802.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	30.00	30.00
2	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	0.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	60.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	700.00	300.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	50.00	0.00
6	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	650.00	300.00
7	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,790.00</b>	<b>690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >