

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003312/KTY3M4**Date:** 16/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00083932101

**Claimant Vehicle No :** SMV5672H **Insured Vehicle No :** SMQ8539S

Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: SNM22D202451/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMV5672H**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UJD2854

Reg. Date: 08/10/2020 (Man. Year: 2019) Chassis No: MMBSTA13AKH003980

Colour: Metallic Pearl White Odometer: 43208 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,904.00	2,151.60	2,752.40	56.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,730.00	2,020.00	53.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,654.00</b>	<b>3,881.60</b>	<b>4,772.40</b>	<b>55.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	8,654.00	3,100.00	5,554.00	64.18
<b>+ GST 7.00/7.00% (S\$)</b>	605.78	217.00	388.78	64.18
<b>Nett Amount (S\$)</b>	<b>9,259.78</b>	<b>3,317.00</b>	<b>5,942.78</b>	<b>64.18</b>

**INSPECTION**

Date of Assignment: 13/04/2022

Date Inspected: 24/05/2022 Inspected At: Cartimes Autolution Pte Ltd  
160 Sin Ming Drive #02-04 Autocity,  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Jun 2022)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5672H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Bent	650.00 FL	*650.00 FL
2	1		*BOOT INNER TRIM	Serviceable	250.00 FL	*- FL
3	1		*BOOT LOCK ASSY	Repair	200.00 FL	*- FL
4	1		*BOOT HINGE LHS	Repair	190.00 FL	*- FL
5	1		*BOOT HINGE RHS	Repair	190.00 FL	*- FL
6	1		*ATTRAGE EMBLEM	Necessary	40.00 FL	*20.00 FL
7	1		*MITSUBISHI EMBLEM	Necessary	50.00 FL	*34.00 FL
8	1		*MIVEC EMBLEM	Necessary	50.00 FL	*32.00 FL
9	1		*REAR BUMPER	Buckled	660.00 FL	*660.00 FL
10	1		*REAR BUMPER RETAINER LHS	Distorted	30.00 FL	*30.00 FL
11	1		*REAR BUMPER REFLECTOR LHS	Serviceable	80.00 FL	*- FL
12	1		*END PANEL	Bent	410.00 FL	*402.00 FL
13	1		*END PANEL TOP GARNISH	Dented / Cut	80.00 FL	*80.00 FL
14	1		*BOOT WEATHERSTRIP	Cut	150.00 FL	*150.00 FL
15	1		*SPARE TYRE PANEL	Repair	990.00 FL	*- FL
16	1		*TAIL LAMP LHS	Cracked	280.00 FL	*266.00 FL
17	1		*TAIL LAMP PANEL LHS	Repair	80.00 FL	*- FL
18	1		*REAR FENDER LHS	Repair	730.00 FL	*- FL
19	1		*REAR FENDER INNER SHIELD LHS	Serviceable	50.00 FL	*- FL
20	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
21	1		*REAR SENSORS	Serviceable	200.00 FS	*- FS
Sub Total (S\$)						5,420.00 2,384.00
- List Item Discount on L Items 10.00/10.00% (S\$)						516.00 232.40
Total Parts (S\$)						4,904.00 2,151.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	1,600.00	800.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,800.00	800.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	20.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	60.00
5	TRANSFER BOOT PARTS	New	150.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>3,750.00</b>	<b>1,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >