

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIANZ INSURANCE SINGAPORE PTE LTD		Ref:	CS/AIS22003315/Uty3n2	
	79 ROBINSON ROAD #09-01 SINGAPORE 068897		Date:	06/05/2022	
			Code:	AIS	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 1125G	Veh. Inspected	GBK 7954U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MLPAISCL202200038FQ	Excess (\$)	0.00	
	Assign From	SHANTI	Assign Date	11/04/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (M)	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	JTFHT02P900250851	Colour	ORANGE	
	Odometer	78818 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15	AUSTONE	6 mm	
	L/H Front Tyre	195 R15	AUSTONE	6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	29/03/2022	Inspection Date	11/04/2022	
	Survey held at LIU'S BROTHER AUTO ENGINEERING WORKSHOP				
		1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	8 Work	ing Days	