

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003316/VNY3Q2**Date:** 17/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00034232101	
Claimant Vehicle No :	SJF3254P	Insured Vehicle No :	GBF9042P	
Date of Loss:	06/04/2022	Nature of Claim:	TP	Claim No: SNM22D202357/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF3254P		Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ E200K, 1.8 (A)		Chassis No:	WDB2110412B068959
Reg. Date:	07/03/2007 (Man. Year: 2007)		Odometer:	161360 km
Colour:	Black			
Engine Capacity:	1796 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R18	Rear Tyre Size:	245/45Z R18
Front Left Side:	Habilead 5 mm	Rear Left Side:	Habilead 5 mm
Front Right Side:	Habilead 5 mm	Rear Right Side:	Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,578.20	18,962.15	29,616.05	60.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,600.00	2,930.00	5,670.00	65.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	57,178.20	21,892.15	35,286.05	61.71
Approved Total (Overridden) (\$\$)		17,000.00		
(\$\$)	57,178.20	17,000.00	40,178.20	70.27
+ GST 7.00/7.00% (\$\$)	4,002.47	1,190.00	2,812.47	70.27
Nett Amount (\$\$)	61,180.67	18,190.00	42,990.67	70.27

INSPECTION

Date of Assignment:	16/04/2022		9006 TAMPINES ST #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840 Repairer:AP AUTO (HQ)
Date Inspected:	12/04/2022	Inspected At:	
Estimated Period of Repair:	7.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2022)
Parts:	143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF3254P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,430.00 FL	*1,280.00 FL
2	1		*FRONT BUMPER FRAME	Dented	116.00 FL	*116.00 FL
3	1		*FRONT BUMPER SIDE FRAME	Dented	61.00 FL	*61.00 FL
4	1		*FRONT BUMPER SIDE BRACKET	O/S Distorted/ N/S Serviceable	170.00 FL	*85.00 FL
5	1		*FRONT BUMPER PROTECTOR RH	Cut	440.00 FL	*440.00 FL
6	1		*FRONT BUMPER CHROME MOULDING RH	Cut	269.00 FL	*269.00 FL
7	1		*FRONT BUMPER SIDE GRILLE RH	No such part	21.00 FL	*- FL
8	1		*FRONT BUMPER LOW GRILLE	Serviceable	78.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	681.00 FL	*400.00 FL
10	2		*FRONT BUMPER REINFORCEMENT ABSORBER	Cracked (1 PCS ONLY)	490.00 FL	*245.00 FL
11	1		*FRONT BUMPER SIDE FRAME RH	Bent	72.00 FL	*72.00 FL
12	1		*FRONT BUMPER SPONGE	No such part	60.00 FL	*- FL
13	1		*FRONT BUMPER BRACKET RH	No such part	87.00 FL	*- FL
14	1		*FRONT BUMPER FOG RH	Cracked	320.00 FL	*320.00 FL
15	1		*FRONT BUMPER FOG LAMP GARNISH RH	Cut	142.00 FL	*142.00 FL
16	1		*FRONT BUMPER LOWER COVER	Cracked	221.00 FL	*221.00 FL
17	1		*FRONT BUMPER NUMBER PLATE GARNISH	Serviceable	160.00 FL	*- FL
18	1		*FRONT HEAD LAMP RH	Cracked	1,125.00 FL	*1,125.00 FL
19	1		*FRONT HEAD LAMP PANEL RH	Cracked	122.00 FL	*122.00 FL
20	1		*FRONT HEAD LAMP WIRE HARNESS	Cut	320.00 FL	*320.00 FL
21	1		*A/C CONDENSER	Not Necessary	1,125.00 FL	*- FL
22	1		*A/C CONDENSER DRIER	No such part	245.00 FL	*- FL
23	2		*A/C CONDENSER HIGH PRESSURE HOSE	Not Necessary	624.00 FL	*- FL
24	2		*A/C CONDENSER LOWER PRESSURE HOSE	Not Necessary	568.00 FL	*- FL
25	1		*RADIATOR	Not Necessary	2,162.00 FL	*- FL
26	1		*RADIATOR FAN	Not Necessary	1,159.00 FL	*- FL
27	2		*RADIATOR FASTENER	Not Necessary	36.00 FL	*- FL
28	1		*RADIATOR TOP HOSE	Not Necessary	82.00 FL	*- FL
29	1		*RADIATOR BOTTOM HOSE	Not Necessary	112.00 FL	*- FL
30	2		*RADIATOR BUSH	Not Necessary	22.00 FL	*- FL
31	1		*RADIATOR BOTTOM TOP AIR DUCT	Not Necessary	512.00 FL	*- FL
32	1		*RADIATOR BOTTOM BOTTOM AIR DUCT	Not Necessary	63.00 FL	*- FL
33	1		*RADIATOR FAN HOUSING	Not Necessary	264.00 FL	*- FL
34	1		*INTERCOOLER	Not Necessary	621.00 FL	*- FL
35	1		*INTERCOOLER INTAKE PIPE	Not Necessary	259.00 FL	*- FL
36	1		*INTERCOOLER OUTLET PIPE	Not Necessary	367.00 FL	*- FL
37	1		*AIR INTAKE HOSE	Cut	320.00 FL	*320.00 FL
38	1		*POWER STEERING COOLER PIPE	Not Necessary	280.00 FL	*- FL
39	2		*FRONT HORN	Not Necessary	284.00 FL	*- FL
40	1		*FRONT BONNET	Dented	2,464.00 FL	*2,464.00 FL
41	1		*FRONT BUMPER LOGO	Necessary	180.00 FL	*180.00 FL
42	1		*FRONT BONNET GRILLE	Cut	512.00 FL	*512.00 FL
43	1		*FRONT BONNET CABLE	Distorted	96.00 FL	*96.00 FL
44	1		*FRONT BONNET INSULATOR	Necessary	148.00 FL	*148.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*FRONT BONNET HINGE	Shifted	268.00 FL	*268.00 FL
46	2		*FRONT BONNET DAMPER	Serviceable	254.00 FL	*- FL
47	1		*FRONT BONNET CENTRE LOCK	Jammed	57.00 FL	*57.00 FL
48	2		*FRONT BONNET SIDE LOCK	Jammed	152.00 FL	*152.00 FL
49	2		*FRONT BONNET LOCK COVER	Cut	92.00 FL	*92.00 FL
50	1		*FRONT BONNET CENTRE UPPER LOCK	Jammed	68.00 FL	*68.00 FL
51	1		*FRONT BONNET STOPPER	Necessary	48.00 FL	*48.00 FL
52	1		*FRONT FENDER RH	Dented	958.00 FL	*958.00 FL
53	1		*FRONT FENDER INNER SHIELD FRONT RH	Cut	172.00 FL	*172.00 FL
54	1		*FRONT FENDER INNER SHIELD REAR RH	Serviceable	180.00 FL	*- FL
55	1		*FRONT FENDER COVER RH	Distorted	210.00 FL	*150.00 FL
56	1		*FRONT DOOR RH TOP HINGE	Serviceable	183.00 FL	*- FL
57	1		*FRONT DOOR RH LOWER HINGE	Serviceable	183.00 FL	*- FL
58	1		*FRONT DOOR RH CHECKER	Missing	152.00 FL	*152.00 FL
59	1		*FRONT WHEEL HOUSE RH	Serviceable	2,712.00 FL	*- FL
60	2		*FRONT CHASSIS END	Repair	444.00 FL	*- FL
61	2		*FRONT CHASSIS END PLATE	Serviceable	314.00 FL	*- FL
62	1		*FRONT SUPPORT PANEL CENTRE	Repair	116.00 FL	*- FL
63	2		*FRONT SUPPORT PANEL LH & RH	Repair	216.00 FL	*- FL
64	2		*FRONT SUPPORT HEADLAMP BRACKET	Cracked	174.00 FL	*174.00 FL
65	1		*FRONT SUPPORT CENTRE BRACE	Repair	76.00 FL	*- FL
66	1		*FRONT SUPPORT WEATHERSTRIP	Not Necessary	176.00 FL	*- FL
67	1		*FRONT SHOCK ABSORBER RH	Bent	866.00 FL	*672.00 FL
68	1		*FRONT SHOCK ABSORBER SPRING RH	Serviceable	378.00 FL	*- FL
69	1		*FRONT SHOCK ABSORBER MOUNTING RH	Serviceable	256.00 FL	*- FL
70	1		*FRONT SHOCK ABSORBER RUBBER BUMPER RH	Serviceable	78.00 FL	*- FL
71	1		*FRONT SHOCK ABSORBER COVER RH	Serviceable	59.00 FL	*- FL
72	1		*FRONT SHOCK ABSORBER DUST CAP RH	Serviceable	39.00 FL	*- FL
73	1		*FRONT UPPER ARM LH	Not Necessary	579.00 FL	*- FL
74	1		*FRONT KNUCKLE ARM RH	Distorted	1,298.00 FL	*1,036.00 FL
75	1		*FRONT KNUCKLE ARM WHEEL HUB BEARING RH	Distorted	795.00 FL	*308.00 FL
76	1		*FRONT LOWER ARM RH	Dented	648.00 FL	*548.00 FL
77	1		*FRONT CONTROL ARM RH	Not Necessary	679.00 FL	*- FL
78	1		*FRONT TIE ROD RH	Dented	146.00 FL	*146.00 FL
79	1		*FRONT LINK ROD RH	Not Necessary	197.00 FL	*- FL
80	1		*FRONT BRAKE ROTOR RH	Serviceable	364.00 FL	*- FL
81	1		*FRONT BRAKE CALIPER RH	Not Necessary	824.00 FL	*- FL
82	1		*FRONT ABS SENSOR RH	Not Necessary	385.00 FL	*- FL
83	1		*FRONT ABS PUMP	Not Necessary	2,800.00 FL	*- FL
84	1		*FRONT AIRBAG SENSOR	Activated	248.00 FL	*248.00 FL
85	1		*AIRBAG SENSOR ECU	Not Necessary	1,976.00 FL	*- FL
86	1		*CURTAIN AIRBAG RH	Necessary	852.00 FL	*852.00 FL
87	1		*FRONT PASSENGER SEAT AIRBAG RH	Activated	783.00 FL	*783.00 FL
88	2		*FRONT SAFETY BELT	Not Necessary	3,750.00 FL	*- FL
89	1		*FRONT WINDSCREEN	Cracked	1,475.00 FL	*1,475.00 FL
90	1		*FRONT WINDSCREEN GARNISH RH	Not Necessary	178.00 FL	*- FL
91	1		*FRONT WINDOW GLASS SENOR	Not Necessary	156.00 FL	*- FL
92	1		*FRONT WIPER GARNISH	Serviceable	352.00 FL	*- FL
93	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
94	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
95	1		*SET FRONT SUPPORT CLIP	Necessary	60.00 FS	*30.00 FS
96	1		*SET FRONT ENGINE UNDERCOVER CLIP	Necessary	80.00 FS	*30.00 FS
97	1		*SET FRONT BUMPER AIR DELECTOR CLIP	Necessary	60.00 FS	*30.00 FS
98	4		*POWER STEERING FLUID	Not Necessary	560.00 FS	*- FS
99	4		*WATER COOLANT	Necessary	276.00 FS	*40.00 FS
100	4		*BRAKE FLUID	Necessary	240.00 FS	*30.00 FS
101	1		*FRONT WINDOW GLASS SOLAR FILM	Necessary	400.00 FS	*150.00 FS

Report was unsubmitted during this print-out.

10/17/22, 3:01 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
102	12		*UNDERCARRIAGE BOLTS	Necessary	144.00 FS	*60.00 FS
103	1		*FRONT WHEEL TYRE (\$500.00) (60%)	Cut	800.00 FS	*300.00 FS
104	1		*SPORT RIM	Cracked	1,800.00 FS	*1,800.00 FS
105	1		*FRONT NUMBER PLATE	Serviceable	55.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					50,891.00	19,827.00
- List Item Discount on L Items 5.00/5.00% (S\$)					2,312.80	864.85
Total Parts (S\$)					48,578.20	18,962.15
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	1,000.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
3	REMOVE AND REFIT UNDERCARRIAGE	New	800.00	150.00
4	CONDUCT CHASSIS ALIGNMENT	New	240.00	120.00
5	CONDUCT 4 WHEEL ALIGNMENT	New	400.00	60.00
6	REMOVE AND REFIT A/C CONDENSER & RADIATOR }	New	400.00	120.00
7	VACCUM AND REFILL A/C GAS }	New	240.00	0.00
8	REFOCUS HEADLIGHTS	New	200.00	60.00
9	TO APPLY RUST PROOFING	New	240.00	100.00
10	REMOVE AND REFIT ABS PUMP BLEEDING	New	320.00	80.00
11	REMOVE AND REFIT A/C CONDENSER & RADIATOR	New	400.00	0.00
12	REPROGRAM ABS PUMP }	New	300.00	120.00
13	REPROGRAM AIRBAG ECU }	New	300.00	0.00
14	ECU DIAGNOSTIC AND CLEARING FAULT CODES }	New	180.00	0.00
15	REMOVE AND REFIT FRONT WINDOW GLASS	New	220.00	120.00
16	REFOCUS HEADLIGHTS	New	120.00	0.00
17	TO APPLY RUST PROOFING	New	240.00	0.00
Gross Labour Cost (\$\$)			8,600.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >