

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122003320/UTY3Q2**Date:** 30/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBE8012M **Insured Vehicle No :** GBE4438U
 Date of Loss: 04/04/2022 Nature of Claim: TP Claim No: CDMCG22000589-002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE8012M**
 Make & Model: BMW 530I, 2.0 LED NAV (A) Engine No: 1KD2604132
 Reg. Date: 28/03/2016 (Man. Year: 2016) Chassis No: JTFHT02P100193884
 Colour: White Odometer: 132701 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm
 Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,752.60	13,396.07	12,356.53	47.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	3,860.00	1,480.00	27.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,092.60	17,256.07	13,836.53	44.50
Approved Total (Overridden) (S\$)		13,800.00		
Nett Amount (S\$)	31,092.60	13,800.00	17,292.60	55.62

INSPECTION

Date of Assignment: 11/04/2022
 Date Inspected: 11/04/2022 Inspected At: LIU'S BROTHER AUTO ENGINEERING WORKSHOP
 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 Estimated Period of Repair: 15.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts: 143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBE8012M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	853.30 F	*- FL
2	1		*FRONT TOYOTA MOTIF	Necessary	82.60 F	*68.10 FL
3	2		*FRONT HEAD LAMP	Holder Cracked	1,861.40 F	*1,561.00 FL
4	1		*FRONT GRILLE INNER	Cracked	138.80 F	*138.80 FL
5	1		*FRONT GRILLE OUTER LOWER	Cracked	665.50 F	*665.50 FL
6	1		*FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
7	1		*FRONT BUMPER	Distorted	796.80 F	*592.00 FL
8	1		*FRONT BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
9	1		*FRONT BUMPER GRILLE	Not Necessary	165.40 F	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	380.40 F	*380.40 FL
11	1		*FRONT NUMBER PLATE (METAL)	Bent	35.00 FS	*20.00 FS
12	1		*FRONT AIRCON CONDENSER	Punctured	1,448.00 F	*1,410.50 FL
13	1		*FRONT RADIATOR	Dented / Punctured	2,372.30 F	*2,115.00 FL
14	1		*FRONT RADIATOR COOLANT	Not Necessary	45.00 F	*- FL
15	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*2,051.60 FL
16	1		*REAR 3RD BRAKE LAMP	Not Necessary	248.50 F	*- FL
17	2		*REAR TAILGATE SUSPENSION	Not Necessary	670.40 F	*- FL
18	1		*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,311.30 F	*1,148.10 FL
19	1		*REAR TAILGATE WINDSCREEN MOULDING	No such part	219.00 F	*- FL
20	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
21	1		*REAR TAILGATE LOCK	Dented / Jammed	264.70 F	*264.70 FL
22	1		*REAR TAILGATE INNER LOCK	Repeated	359.00 F	*- FL
23	1		*REAR TAILGATE WEATHERSTRIP	Twisted	391.20 F	*391.20 FL
24	1		*REAR TAILGATE INNER TRIM BOARD	Torn	197.40 F	*197.40 FL
25	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	88.00 F	*50.00 FL
26	1		*REAR NUMBER PLATE (METAL)	Serviceable	35.00 FS	*- FS
27	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	277.20 F	*- FL
28	1		*REAR TAILGATE NUMBER PLATE LAMP OUTER GARNISH	Bent / Cracked	346.50 F	*346.50 FL
29	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
30	1		*REAR TAILGATE TOYOTA EMBLEM	Not Necessary	82.90 F	*- FL
31	1		*REAR HIACE EMBLEM	Not Necessary	78.30 F	*- FL
32	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
33	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
34	2		*REAR TAIL LAMPS	Broken / Cracked	730.20 F	*730.20 FL
35	1		*REAR TAIL LAMP PANEL LH	Badly Dented	936.20 F	*651.10 FL
36	1		*REAR BUMPER	Distorted	599.30 F	*465.00 FL
37	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*40.00 FS
38	1		*REAR BUMPER STEP PANEL	Not fitted	262.30 F	*- FL
39	4		*REAR BUMPER BRACKET	Bent	404.00 F	*100.00 FL
40	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
41	1		*REAR SPARE TYRE CARRIER	Serviceable	345.20 F	*- FL
42	1		*REAR END PANEL INNER	Badly Dented	936.20 F	*936.20 FL
43	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
44	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR FENDER LH(BODY PANEL)	Buckled / Badly Dented	1,145.10 F	*1,145.10 FL
46	1		*REAR CORNER PANEL GARNISH LH	Cracked	185.80 F	*185.80 FL
47	1		*REAR FLOOR PANEL	Repair	1,855.90 F	*- FL
48	1		*REAR FLOOR PANEL BEAM	Distorted	277.80 F	*277.80 FL
49	1		*REAR FLOOR PANEL TOP WOODEN BOARD	Cracked	650.00 FS	*480.00 FS
50	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	450.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,752.60	17,518.10
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	4,122.03
Total Parts (\$)	25,752.60	13,396.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	120.00	30.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
3	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
4	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	50.00
5	TO REMOVE & REFIX AIR CON ,REFILL AIR CON GAS & TEST FOR LEAKAGES	New	280.00	100.00
6	LABOR FOR PANEL BEATING ,CUT ,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	2,800.00	2,000.00
7	TO REMOVE & REPLACE RADIATOR & CONDUCT PRESSURE TEST AND BLEED SYSTEM	New	180.00	0.00
8	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,500.00	1,400.00
9	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	180.00	100.00
Gross Labour Cost (\$)			5,340.00	3,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >