

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6616T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	896.20	-
1	REAR BUMPER BOTTOM REINFORCEMENT (SN)	NOT NECESSARY	75.95	-
1	REAR BUMPER TRIM STRIP (SN)	NOT NECESSARY	107.35	-
1	REAR BUMPER PANEL PRIMED (PDC/PMA)(SN)	DENTED	1,603.00	1,603.00
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			2,762.50	1,683.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER AND ATTACHMENTS.		1,275.00	850.00
	TO PAINTING REAR BUMPER.		1,038.00	986.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	168.00
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
			2,667.00	2,172.00
	GRAND TOTAL		5,429.50	3,855.00

RECOMMENDED COST OF REPAIRS 3,855.0

Report Ref No. CS/SMR22003321/Eqy3n2

CHEN TSUE YEE

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator