

ASS. REC. BY:

REF:

CS/0012003323/A y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMQ83636 Regn: 2016 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima C.C. 2362Colour: Black A/C: Insured / Std / NI / NASp. Reading: 122532 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR507126784Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R18R: 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/04/22Survey held at Ryder

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 401Lump Sum \$ 6400 and 6 days
(Red. \$ 8623.58, 57%)

MV:

PV:

Nett:

Date/Time, File Pass to?

1) 5/8/22

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / L.P. Fee 6400

: Preli. Report



: Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



Survey Fee:

Transportation:

S + RS. SI

Photos

Others

ESTIMATE OF REPAIR

Veh# : SMQ8363G

Model:

TOYOTA ESTIMA

Accident Date : 11/4/2022

10/12/2016

Location : CTE (CITY) BEFORE BRADDELL ROAD EXIT

3P:

GBG971L (UOI)

S/No	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Dehnd</i>	1,623.20	881	
2	10 pcs	Rear bumper clips <i>Nu</i>		80.00	30
3	2pcs	Rear bumper screw middle <i>Nu</i>		20.00	+
4	1 pc	Rear bumper o/s retainer <i>Nu</i>	118.20	✓	
5	1 pc	Rear bumper o/s retainers middle <i>Nu</i>	98.40	✓	
6	1 pc	Rear bumper o/s reflector <i>Nu</i>	260.80	✓	
7	1 pc	Rear bumper chrome moulding <i>Nu</i>		200.00	X
8	1 pc	Rear reverse sensor <i>Dehnd</i>	1,430.40	200 (SN)	
9	1 pc	Rear tail gate o/s reflector <i>Nu</i>	525.30	373	
10	1 pc	Rear o/s tail lamp <i>Nu</i>	599.60	✓	
11	1 pc	Rear tail gate <i>Dehnd</i>	2,445.60	1485	
12	1 pc	Rear tail gate toyota emblem <i>Nu</i>	130.70	68	
13	1 pc	Rear tail gate Estima emblem <i>Nu</i>	86.60	60	
14	1 pc	Rear tail gate AERAS emblem <i>Nu</i>	78.20	✓	
15	1 pc	Rear o/s tail gate inner trim <i>Nu</i>	712.50	✓	
16	1 pc	Rear tail gate inner trim <i>Nu</i>	542.40	✓	
17	16 pcs	Rear tail gate inner trim clips <i>Nu</i>		80.00	50
18	1 pc	Rear tail gate lock (Upper) <i>Nu</i>	577.10	✓	
19	8pcs	Rear o/s fender inner trim clips <i>Nu</i>		40.00	X
20	1 pc	Rear o/s fender inner trim <i>Nu</i>	810.20	✓	
21	1 pc	Rear o/s fender <i>Dehnd</i>	1,520.50	1150	
22	1 pc	Rear quarter glass moulding <i>Nu</i>		140.60	
23	1 pc	Rear quarter glass sealant <i>Nu</i>		60.00	40
24	1 pc	Rear windscreen <i>Shattered</i>	1,180.40	✓	
25	1 pc	Rear windscreen moulding <i>Nu</i>		210.40	✓
26	1 pc	Rear windscreen sealant <i>Nu</i>		80.00	60
27	1 pc	Rear solar film 3M <i>Nu</i>		500.00	280
28	1 pc	Rear wiper <i>Nu</i>		80.00	X
		Sub Total:	12,790.10	1,491.00	0.00
			25%	0%	10%
		After Less %:	9,592.58	1,491.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		1,500.00	900
2		To spray painting.		1,200.00	600
3		To remove & refit rear windscreen.		160.00	120
4		To remove & replace rear reverse sensor		80.00	50
5		To remove & replace rear reverse camera		80.00	50
6		To remove & replace rear tail gate. <i>Fitting</i>		100.00	80
7		To remove & refit rear o/s quarter glass		140.00	60
8		To remove and refit rear upholstery to facilitate repair		150.00	60
9		To check for fault code and resetting		250.00	X
10		To check wiring.		80.00	30
11		To re seal anti rust.		100.00	80
		Sub Total:		3,940.00	
		Total:		15,023.58	
		After less 20%		12,018.86	

L&K Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

663420 SN 991
497565

2030

Total: 7996.65

1/5: 6.4K

06 Days

6.4K