

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 12/4/2022

Steven@lkk.com

RE: VEHICLE REPAIR QUOTATION

Insurance Company

Vehicle Reg No

Name of Insured

Policy Number

Date of Accident

Tyre of Claim

Model

Chassis No

Stev (LKK) 83228813

14/4/22, 11.30am

ML PL

PIP

3 days

CHINA TAIPING INSURANCE
SMW3939Y

Third Party Claim
MB GLC300
W1N2533842F814067

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT BUMPER (10) X R	\$ 1,708.65	
2	FRONT BUMPER CORNER TRIM (50) - RC CUT	\$ 76.77	
3	SENSOR (290) ? X nn	\$ 193.12	
4	SENSOR RING / M 38x6pc	\$ 8.00	
5	BUMPER CLIPS (10 PCS) - M	\$ 16.00	
6	BUMPER RETAINER RH (130) ? X nn	\$ 29.02	
7	BUMPER BRACKET (30) ? X nn	\$ 67.30	
8	FRONT RH WHEEL ARCH ? X nn	\$ 201.02	
9	FRONT BUMPER LOWER TRIM (415) ? X nn	\$ 381.24	
10	CLIPS (360) 4 PCS ? X nn	\$ 8.00	
11	FRONT BUMPER RH CHROME TRIM (420) X nn	\$ 117.57	
12	RIM X nn	\$ 1,858.57	

Sub Total Parts \$ 4,665.26
Less 10% \$ 466.53
Total Parts \$ 4,198.73

154.77
-10%
139.29

1	Sundries	\$ 70	150.00
2	Wiring connection and check.	\$ 40	150.00
3	Tuff kote and spray anti rust proofing	\$ 30	150.00
4	Labour charges to dismantle & refix front bumper front lower bumper & adjust affected portion to specific dimension.	\$ 200	600.00
5	To conduct 4 wheel alignment	\$ X	900.00
6	To remove and refix front radar sensor SCN coding, calibration and test drive	\$ 100	350.00
7	To program ESP control module for front parking sensor -	\$ X	350.00
8	To spray paint front bumper front rh fender and all other accident affected portion	\$ 230	750.00

630
P/P = 769.29