

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8344U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	503.04	503.04
1	REAR BUMPER LOWER COVER	SCRATCHED	654.96	654.96
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	378.32	-
1	REAR CENTRE UNDER COVER	SERVICEABLE	425.25	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	55.00	-
1	REAR BUMPER TOW COVER	SCRATCHED	82.70	82.70
1	REAR TRUNK LOGO PRIUS	NOT NECESSARY	52.90	-
1	REAR TRUNK LOGO HYBRID	NOT NECESSARY	52.40	-
2	REAR BUMPER SIDE RETAINER LH/RH @\$112.70	SERVICEABLE	225.40	-
10	REAR BUMPER CLIP @\$2.20	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-612.99	-315.68
			1,838.98	947.02
	NETT ITEMS			
1	BOOTLID COMFORT & TEL NUMBER (N)	NOT NECESSARY	60.00	-
1	BOOTLID COMFORT APP (N)	NOT NECESSARY	40.00	-
1	BUMPER REVERSE SENSOR (N)	SERVICEABLE	135.70	-
	LESS 10% DISCOUNT		-23.57	-
			212.13	-
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	CHECK WIRING AND LIGHTING.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,420.00	660.00
	GRAND TOTAL		3,471.11	1,607.02





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,300.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22003331/Vty3n2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser