

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22003347/GEA3Q2**Date:** 15/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070110420
Claimant Vehicle No :	SMP5130L	Insured Vehicle No :	EF6969A
Date of Loss:	09/04/2022	Nature of Claim:	TP
		Claim No:	1478851957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5130L		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK086288
Reg. Date:	28/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF44KA104996
Colour:	Black	Odometer:	17633 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,684.00	2,022.00	12,662.00	86.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,272.00	2,850.00	55.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,806.00	4,294.00	15,512.00	78.32
+ GST 7.00/7.00% (S\$)	1,386.42	300.58	1,085.84	78.32
Nett Amount (S\$)	21,192.42	4,594.58	16,597.84	78.32
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,996.58		

INSPECTION

Date of Assignment:	11/04/2022		
Date Inspected:	13/04/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	254.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	72.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Cut	151.00 FS	*120.40 FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	41.00 FS	*- FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
9	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
10	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
11	1		*FRONT FENDER -RH	Repair	861.00 FS	*- FS
12	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
13	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	81.00 FS	*- FS
14	1		*FRONT FENDER BRACKET -RH	Not Necessary	41.00 FS	*- FS
15	6		*FRONT FENDER POP RIVET	Not Necessary	23.00 FS	*- FS
16	1		*FRONT FENDER BRACE -RH	Not Necessary	132.00 FS	*- FS
17	1		*FRONT FENDER BRACKET CENTER -RH	Not Necessary	55.00 FS	*- FS
18	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	262.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
20	1		*FRONT WHEEL SPOILER -RH	Not Necessary	82.00 FS	*- FS
21	1		*FRONT WHEEL SPOILER LOWER -RH	Not Necessary	40.00 FS	*- FS
22	1		*FRONT FENDER LEDGE COVER LONG -RH	Not Necessary	35.00 FS	*- FS
23	1		*FRONT FENDER LEDGE COVER SHORT-RH	Not Necessary	26.00 FS	*- FS
24	1		*HEADLIGHT -RH	Not Necessary	8,294.00 FS	*- FS
25	1		*LIFT CYLINDER -RH	Not Necessary	231.00 FS	*- FS
26	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,684.00 2,022.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RNEEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >