



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 4488M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH (N) (CONSISTENT)	BENT	675.00	675.00
1	FRONT DOOR -LH (N) (CONSISTENT)	BENT	1,880.00	1,880.00
1	FRONT DOOR WEATHERSTRIP -LH (N) (CONSISTENT)	NECESSARY	328.00	328.00
	LESS 10% DISCOUNT		-288.30	-288.30
			2,594.70	2,594.70
20	FRONT DOOR TRIMBOARD RIVETS -LH @\$12.00 (SN) (CONSISTENT)	NECESSARY	240.00	60.00
	LESS 10% DISCOUNT		-24.00	-
			216.00	60.00
	<u>LABOUR</u>			
	TO TRANSFER LH FRONT DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR .		150.00	60.00
	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER INNER PANEL ,LH FRONT DOOR PILLAR ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME.		1,000.00	400.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS .		1,000.00	440.00
			2,230.00	920.00
GRAND TOTAL			5,040.70	3,574.70
RECOMMENDED COST OF REPAIRS				3,574.70

Report Ref No. CC4/ASM22003349/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.