

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003350/UPA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000070
Claimant Vehicle No :	GBC4246S	Insured Vehicle No :	GBH7479R
Date of Loss:	02/04/2022	Nature of Claim:	TP
		Claim No:	7501617553SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC4246S		
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Engine No:	1KD2197221
Reg. Date:	04/06/2012 (Man. Year: 2012)	Chassis No:	JTFAT35Y30K202001
Colour:	White	Odometer:	301405 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6/6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.96	1,130.00	822.96	42.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,600.00	380.00	19.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,932.96	2,730.00	1,202.96	30.59
+ GST 7.00/7.00% (\$\$)	275.31	191.10	84.21	30.59
Nett Amount (\$\$)	4,208.27	2,921.10	1,287.17	30.59
+ Car Rental (\$\$)		1,070.00		
Nett Liability (\$\$)		3,991.10		

INSPECTION

Date of Assignment:	13/04/2022		
Date Inspected:	13/04/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRAME ,DRIVER SIDE VERTICAL (O/S)	Distorted	580.00 FS	*580.00 FS
2	1		*REAR DOOR RIGHT BOTTOM HINGE	Bent	200.00 FS	*150.00 FS
3	1		*GRP BOARD (O/S)	Cracked	1,000.00 FS	*400.00 FS
4	1		*REAR TAILLAMP (Damaged)	Not Consistent With The Impact	172.96 FS	*- FS
					Total Parts (S\$)	1,952.96 1,130.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY ADHESIVE TO FIX THE ABOVE ARGON WELDING AT JOINT OF STAINLESS STEEL DOOR	New	180.00	0.00
2	FRAME & TO DISMANTLE & REPLACE WITH THE ABOVE ITEM	New	1,800.00	1,600.00
Gross Labour Cost (S\$)			1,980.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >