

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22003356/Vty3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 06/05/2022 SINGAPORE 068811 ATTN: NG STACEY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 3517R GBH 34L Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03Y9V Excess (\$) 0.00 **Assign Date** NG STACEY 12/04/2022 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA DYNA 150** Make & Model 2982 c.c HIDDEN 2017 Engine No. Year of Reg. JTFAT35Y10K209612 WHITE Chassis No. Colour 130323 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C ARIVO 5 mm ARIVO L/H Front Tyre 195 R15C 5 mm 195 R15C ARIVO R/H Rear Tyre 5 mm **ARIVO** L/H Rear Tyre 195 R15C 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 09/04/2022 12/04/2022 ( 05:00 PM ) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/ASM22003356/Vty3e2

**Estimate Days of Repair** 

**Inspected By** 

5b.

THEVAN THOMAS KARTHIKESAVAN

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days