

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III22003358/KNY3E2**Date:** 27/09/2022**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326\_01

Date of Loss: 16/03/2022

Nature of Claim: OD

Claim No: MFL2022D0001358

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNB4373X</b>	Engine No:	G4FGMH703126
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416MM5107423
Reg. Date:	23/08/2021 (Man. Year: 2021)	Odometer:	2427 km
Colour:	Metallic Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 9 mm	Rear Left Side:	Nexen 9 mm
Front Right Side:	Nexen 9 mm	Rear Right Side:	Nexen 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,646.80	3,412.20	3,234.60	48.66
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	4,120.00	2,980.00	1,140.00	27.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,777.80</b>	<b>6,403.20</b>	<b>4,374.60</b>	<b>40.59</b>
<b>- Excess (S\$)</b>	0.00	750.00	-750.00	
<b>(S\$)</b>	10,777.80	5,653.20	5,124.60	47.55
<b>+ GST 7.00/7.00% (S\$)</b>	754.45	395.72	358.73	47.55
<b>Nett Amount (S\$)</b>	<b>11,532.25</b>	<b>6,048.92</b>	<b>5,483.33</b>	<b>47.55</b>

**INSPECTION**

Date of Assignment:	12/04/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	12/04/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	8.0 days		

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2022)
<b>Parts:</b> 143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNB4373X)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Bent	1,138.00 FL	*1,138.00 FL
2	1		*LH REAR DOOR GLASS	Cut	181.00 FL	*181.00 FL
3	2		*LH REAR DOOR GLASS BLACK STICKER	Necessary	30.00 FL	*30.00 FL
4	1		*LH REAR FENDER	Bent	1,133.00 FL	*1,133.00 FL
5	1		*LH REAR FENDER INNER SHIELD	Serviceable	75.00 FL	*- FL
6	10		*LH REAR FENDER INNER SHIELD CLIPS	Not Necessary	75.00 FL	*- FL
7	1		*LH REAR FENDER 1/4 GLASS	Serviceable	252.00 FL	*- FL
8	1		*FUEL LIP COVER	Cracked	54.00 FL	*54.00 FL
9	1		*FUEL LIP COVER INNER	Serviceable	60.00 FL	*- FL
10	1		*LH REAR RIM R16	Dented	926.00 FL	*926.00 FL
11	1		*LH REAR SHOCK ABSORBER	Serviceable	231.00 FL	*- FL
12	1		*LH REAR KNUCKLE BEARING	Not Necessary	437.00 FL	*- FL
13	1		*REAR AXEL ASSY	Serviceable	1,031.00 FL	*- FL
14	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
15	1		*INNER SEAL	Necessary	30.00 FS	*30.00 FS
16	2		*FRT DOOR BLACK STICER	Scratched	36.00 FL	*36.00 FL
17	1		*FUEL CAP	Serviceable	112.00 FL	*- FL
18	1		*REAR WINDSCREEN GLASS WITH MOULDING	Not Necessary	1,321.00 FL	*- FL
<b>Supplementary #1</b>						
19	1		*FUEL LID BASE BRACKET	Cracked	60.00 FL	*60.00 FL
20	1		*REAR LH DOOR GLASS SOLAR FILM	Necessary	140.00 FS	*140.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,362.00</b>	<b>3,768.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	715.20	355.80
<b>Total Parts (S\$)</b>	<b>6,646.80</b>	<b>3,412.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO CUT, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS LH REAR FENDER, LH REAR DOOR, LH SIDE ROOF TOP PANEL, REAR BUMPER AND ETC	New	1,440.00	1,080.00
3	TO TRANSFER LH REAR DOOR INNER PARTS FROM DAMAGE TO NEW	New	120.00	80.00
4	TO REMOVE AND INSTALL REAR UNDER CARRIAGE	New	240.00	0.00
5	TO CONDUCT WHEEL ALGINMENT	New	80.00	60.00
6	TO REMOVE AND INSTALL REAR SEAT, FUEL TANK, LH REAR FENDER INNER TRIM, SPARE TYRE BOARD TO FACILITATE REPAIR	New	180.00	120.00
7	TO REMOVE AND INSTALL ROOF LINING	New	240.00	80.00
8	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS LH FRT FENDER, LH FRT DOOR, LH REAR FENDER, LH REAR DOOR, LH SIDE ROOF TOP PANEL, REAR BUMPER AND ETC	New	1,700.00	1,440.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,120.00</b>	<b>2,980.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**