

# LCL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Farah Atikah Binte Sukri  
C/o: Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park, Singapore 408934

Date : 19 April 2021  
Our ref : TWG/04/2101/TP

Accident Date : 01 April 2021  
Inspection Date : 07 April 2021  
Repairer Name : Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park, Singapore 408934

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No	: SMX 9237 U	Year / Capacity	: 2009 / 2979 cc
Make / Model	: BMW 335i	Colour	: Blue
Chassis No	: WBAPM72080A381029	Mileage	: 151278
Engine No	: 06706958N54B30A		

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Tourador	235/35 R19	5 mm	Sport
Front Offside	: Tourador	235/35 R19	5 mm	Sport
Rear Nearside	: Tourador	235/35 R19	5 mm	Sport
Rear Offside	: Tourador	235/35 R19	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 67 copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$9,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No.: SMX 9237 U

Our Ref No.:

TWG/04/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear boot lid	Repair	\$ 1,658.00	
1	Rear boot logo	Necessary	\$ 79.00	\$ 79.00
1	Rear boot rubber	Intact	\$ 225.00	XNN
1	Rear boot "523I" emblem	Necessary	\$ 89.50	\$ 89.50
1	Rear n/s taillamp	Damage	\$ 655.00	\$ 655.00
1	Rear bumper	Damage	\$ 1,495.00	\$ 1,495.00
2	Rear bumper brackets	Damage	\$ 98.00	\$ 98.00
1	Rear bumper centre moulding	Damage	\$ 248.10	\$ 248.10 CRA
1	Rear bumper inner frame garnish	Damage	\$ 335.00	\$ 335.00 XNN
1	Rear bumper lower diffuser	Damage	\$ 685.00	\$ 685.00
1	Rear bumper reinforcement	Damage	\$ 685.00	\$ 685.00 XNN
2	Rear bumper side retainers	Necessary	\$ 279.90	\$ 279.90
2	Rear bumper PDC sensors	Damage	\$ 718.00	\$ 718.00 550
			<b>\$ 7,250.50</b>	<b>\$ 5,367.50</b>
Less 5%			\$ 362.53	\$ 268.38
<b>Total Cost - List Items</b>			<b>\$ 6,887.98</b>	<b>\$ 5,099.13</b>

## SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00 50
1	Rear exhaust assy	Damage	\$ 4,000.00	\$ 4,000.00 X R
1	Exhaust chrome tail pipe set	Damage	\$ 500.00	\$ 500.00 400
<b>Total Cost - Special Nett items</b>			<b>\$ 4,560.00</b>	<b>\$ 4,560.00</b>

Local repair  
\$500 (500)

5 days

**Total cost of parts**

**\$ 11,447.98 \$ 9,659.13**

Vehicle Registration No.: SMX 9237 U

Our Ref No.: TWG/04/2101/TP

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

**Total cost of parts c/f**

\$ 11,447.98 \$ 9,659.13

### LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 60
3	To remove and refit rear reverse sensor.	\$ 150.00	\$ 120.00 50
4	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 150.00	\$ 120.00 X
5	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 X
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,000.00	\$ 750.00 400
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ 880.00 500

**GRAND TOTAL**

\$ 14,277.98 \$ 11,759.13



Vehicle Registration No.: SMX 9237 U

Our Ref No.: TWG/04/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 9,400.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be void.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**

  
\_\_\_\_\_  
Cheong K. H  
Automotive Appraiser