

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22003361/Vvy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 10/05/2022 SINGAPORE 068811 ATTN: KHONG LYNN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. YP 5498J Veh. Inspected **SLG 3259Y** Policy No. GA607174 Coverage (\$) 0.00 Claim No. S2M03Y7M Excess (\$) 0.00 KHONG LYNN 12/04/2022 Assign From Assign Date 2. **Vehicle Particulars & Condition** TOYOTA HARRIER PERMIUM c.c Make & Model 1986 HIDDEN 2016 Engine No. Year of Reg. ZSU600070203 RED Chassis No. Colour Odometer 241028 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Make Size **Balance** R/H Front Tyre 235/70 R16 BRIDGESTONE 6 mm L/H Front Tyre 235/70 R16 BRIDGESTONE 6 mm 235/70 R16 BRIDGESTONE R/H Rear Tyre 6 mm BRIDGESTONE L/H Rear Tyre 235/70 R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 06/04/2022 Inspect Date / Time 12/04/2022 (06:00 PM) Accident Date YEOW KOON MOTOR SPRAY PAINTING Survey held at BLK 9002 TAMPINES STREET 93 #01-34 TAMPINES INDUSTRIAL PARK A SINGAPORE 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22003361/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

8 Working Days