

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003365/KQY3N2**Date:** 29/06/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSAW000017012201
Claimant Vehicle No :	SKD7787R	Insured Vehicle No :	YP1341D
Date of Loss:	26/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D202166/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD7787R	Engine No:	PY10264672
Make & Model:	MAZDA CX-5, 2.5 (A)	Chassis No:	JM6KF2WLAJ0103212
Reg. Date:	31/07/2017 (Man. Year: 2017)	Odometer:	121632 km
Colour:	Metallic Pearl White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55ZR19	Rear Tyre Size:	235/55ZR19
Front Left Side:	Habilead 5 mm	Rear Left Side:	Habilead 5 mm
Front Right Side:	Habilead 5 mm	Rear Right Side:	Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,351.00	2,852.48	4,498.52	61.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	660.00	1,990.00	75.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,001.00	3,512.48	6,488.52	64.88
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	10,001.00	2,800.00	7,201.00	72.00
+ GST 7.00/7.00% (\$\$)	700.07	196.00	504.07	72.00
Nett Amount (\$\$)	10,701.07	2,996.00	7,705.07	72.00

INSPECTION

Date of Assignment:	12/04/2022	
Date Inspected:	24/05/2022 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
Parts:	M1-SUV	MAZDA CX-5 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD7787R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,550.90 F	*- FL
2	1		*FRONT FENDER-RH	Repair	625.10 F	*- FL
3	1		*FRONT FENDER PROTECTOR-RH	Serviceable	195.00 F	*- FL
4	1		*FRONT HEADLAMP-RH	Cut	4,795.00 F	*3,565.60 FL
5	1		*GRILLE CHROME-RH	Serviceable	185.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	7,351.00 3,565.60
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 713.12
					Total Parts (\$\$)	7,351.00 2,852.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,000.00	200.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,000.00	440.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	100.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
5	COMPUTER DIAGNOSTIC	New	250.00	0.00
6	SUPPLY PAINTING MATERIAL	New	200.00	0.00
Gross Labour Cost (\$\$)			2,650.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >