



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 5431J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER SIDE REAR RH (WHITE) (CUT)	NOT CONSISTENT WITH THE IMPACT	28.00	-
1	EMBLEM (YAMAHA) LOGO	NOT NECESSARY	14.00	-
1	HEADLAMP ASSY	CRACKED	299.00	299.00
1	LAMP SIGNAL FRONT RH	NOT NECESSARY	35.00	-
1	MUDGUARD FRONT (WHITE)	CRACKED	45.00	45.00
1	PANEL 2 (GREY) RH	NOT NECESSARY	21.00	-
2	STICKER (CERTIS CISCO) LOGO NEW MODEL LH / RH	NOT NECESSARY	42.00	-
1	STICKER (CISCO) LINING COVER REAR RH	NOT NECESSARY	15.00	-
	LESS 10% DISCOUNT		-	-34.40
			499.00	309.60
<u>SPECIAL NETT ITEMS</u>				
1	STICKER (CISCO) MUDGUARD FRONT (SN)	NECESSARY	35.00	35.00
			35.00	35.00
<u>LABOUR</u>				
	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.		252.00	120.00
	SPRAY LACQUER COVER SIDE REAR RH.	NOT NECESSARY	63.00	-
	SPRAY LACQUER MUDGUARD FRONT.		50.00	30.00
	TRANSPORT CHARGES.		56.00	40.00
			421.00	190.00
GRAND TOTAL			955.00	534.60
RECOMMENDED COST OF REPAIRS				534.60

Report Ref No. CS/FCI22003374/Uty3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.