



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22003374/Uty3e2	
			Date: 06/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3219G	Veh. Inspected	FBN 5431J
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22001051MFVS	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	12/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MH3SG431000008373	Colour	WHITE
	Odometer	69615 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110-70-13	TIMSUN	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130-70-13	DUNLOP	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/04/2022	Inspection Date	12/04/2022
	Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	