



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 8868K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER SENSOR RH (CONSISTENT)	SERVICEABLE	312.00	-
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,897.00	-
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	NOT NECESSARY	211.00	-
1	FRONT BUMPER SIDE GARNISH RH(CONSISTENT)	NOT NECESSARY	312.00	-
1	LED HEADLAMP RH (CONSISTENT)	SCRATCHED / CRACKED	3,985.00	3,029.47
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,210.00	-
1	FRONT FENDER COWLING RH (CONSISTENT)	NOT NECESSARY	212.00	-
1	FRONT KNUCKLE ARM RH (CONSISTENT)	NOT NECESSARY	989.00	-
1	FRONT WHEEL WITH BEARING RH(CONSISTENT)	NOT NECESSARY	587.00	-
	LESS 10% DISCOUNT		-971.50	-302.95
			8,743.50	2,726.52
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	50.00	50.00
1	SET FRONT FENDER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT SPORTS RIM RH (SN)(CONSISTENT)	NOT NECESSARY	1,500.00	-
			1,600.00	50.00
<u>LABOUR</u>				
	SPRAY PAINTING ON AFFECTED AREAS .		600.00	400.00
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER RH .		600.00	420.00
	TO CHECK ELECTRICAL WIRING.		120.00	20.00
	TO REMOVE AND REFIT FRONT BUMPER SENSOR .		150.00	40.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	500.00	-
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	CHECK AND RESET FAULT CODE LIGHT ON .		400.00	100.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	150.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	200.00	-
			2,840.00	980.00
GRAND TOTAL			13,183.50	3,756.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/ASM22003378/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.