

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Ref:	CS3/ASM22003379/Ety3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	05/05/2022	
	ATTN: KOH JANIC	E	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKN 6693G	Veh. Inspected	SLC 1022Y	
	Policy No.	GA486771	Coverage (\$)	0.00	
	Claim No.	S2M03YBR	Excess (\$)	0.00	
	Assign From	KOH JANICE	Assign Date	12/04/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	MR053REH104547186	Colour	GREY	
	Odometer	70315 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	MICHELIN	4 mm	
	L/H Front Tyre	195/55 R15	MICHELIN	4 mm	
	R/H Rear Tyre	195/55 R15	MICHELIN	4 mm	
	L/H Rear Tyre	195/55 R15	MICHELIN	4 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	11/04/2022	Inspect Date / Time	13/04/2022 (08:16 PM)	
	Survey held at	TIAN SIANG MOTOR			
		27-A JURONG PORT ROAD #01-19, JURONG INDUSTRIAL ESTATE SINGAPORE 619101			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				

Report Ref No. CS3/ASM22003379/Ety3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days