

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22003383/AQY3Q2**Date:** 04/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GZ5837A **Insured Vehicle No :** YQ3082H

Date of Loss: 11/04/2022 Nature of Claim: TP Claim No: CDMCG22000659

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ5837A**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 5L5655113

Reg. Date: 29/06/2006 (Man. Year: 2006) Chassis No: JTFUF34Y503011969

Colour: Silver Odometer: 393647 km

Engine Capacity: 2986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14C Rear Tyre Size: 155 R12C

Front Left Side: TRANSITO 6 mm Rear Left Side: Condor 6 mm

Front Right Side: TRANSITO 6 mm Rear Right Side: Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,904.36	11,012.60	8,891.76	44.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,750.00	3,780.00	1,970.00	34.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,654.36	14,792.60	10,861.76	42.34
Approved Total (Overridden) (S\$)		11,800.00		
Nett Amount (S\$)	25,654.36	11,800.00	13,854.36	54.00

INSPECTION

Date of Assignment: 12/04/2022

Date Inspected: 13/04/2022 Inspected At: Unimotor Co (HQ)
NO 1 KAKI BUKIT AVE 6 #01-94
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jan 2023)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ5837A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H DOOR PILLAR ASSY	Distorted	1,233.80 FL	*895.00 FL
2	1		*FRONT R/H DOOR PILLAR ASSY	Repair	1,233.80 FL	*- FL
3	1		*FRONT R/H MUDFLAT PLATE	Not Necessary	286.40 FL	*- FL
4	1		*FRONT RADIATOR SPARE TANK	Not Necessary	112.40 FL	*- FL
5	2		*FRONT RUBBER HOLDING	Not Necessary	168.80 FL	*- FL
6	1		*FRONT AIR CLEARING HOUSING	Cracked	878.60 FL	*396.00 FL
7	1		*FRONT AIR CLEARING JOINT	Distorted	204.40 FL	*204.40 FL
8	1		*REAR TAILGATE ASSY	Distorted	1,456.30 FL	*1,456.30 FL
9	4		*REAR TAILGATE HINGES	Bent	157.20 FL	*157.20 FL
10	1		*REAR TAILGATE TOYOTA STICKER	Not Necessary	236.80 FL	*- FL
11	1		*REAR TAILGATE DYNA STICKER	Necessary	41.20 FL	*41.20 FL
12	1		*REAR TAILGATE LOCK HANDER (LOWER)	N/S Distorted	312.40 FL	*89.00 FL
13	1		*REAR TAILGATE LOWER LOCK ARM	N/S Distorted	530.60 FL	*198.00 FL
14	1		*REAR TAILGATE LOWER MEMBER	Not Necessary	485.90 FL	*- FL
15	1		*REAR TAILGATE STOPPER RUBBER	N/S Missing	146.40 FL	*35.00 FL
16	1		*REAR TAILGATE RUBBER BRACKET	N/S Bent	291.20 FL	*145.60 FL
17	2		*REAR COMBINATION LAMP ASSY	Cracked	627.60 FL	*570.00 FL
18	2		*REAR COMBINATION LAMP BRACKET	Bent	267.80 FL	*267.80 FL
19	1		*REAR NUMBER PLATE BRACKET	Distorted	159.60 FL	*159.60 FL
20	1		*REAR NUMBER PLATE LAMP	Cracked	48.60 FL	*48.60 FL
21	1		*REAR CENTRE CHASSIS CROSSMEMBER	Repair	855.62 FL	*- FL
22	1		*REAR SPARE WHEEL CARRIER	Not Necessary	386.60 FL	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	589.80 FL	*- FL
24	2		*REAR MUDFLAT (L AND R)	Not Necessary	691.20 FL	*- FL
25	1		*REAR FLOOR BOARD PANEL	Distorted	7,500.00 FS	*6,000.00 FS
26	1		*L/H SIDE GATE PANEL ASSY	Dented	1,553.10 FL	*1,553.10 FL
27	1		*R/H SIDE GATE PANEL ASSY	Repair	1,553.10 FL	*- FL
28	4		*L/H SIDE GATE HINGES	Not Necessary	157.20 FL	*- FL
29	4		*R/H SIDE GATE HINGES	Not Necessary	157.20 FL	*- FL
30	1		*REAR EXHAUST PIPE	Not Necessary	779.60 FL	*- FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	42.60 FL	*- FL
32	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
33	1		*REAR TAILGATE (70KM/H) STICKER	Necessary	20.00 FS	*10.00 FS
34	1		*REAR TAILGATE (13PAX) STICKER	Necessary	20.00 FS	*10.00 FS
35	1		*SET SIDE AND REAR COMPANY STICKER	Necessary	500.00 FS	*300.00 FS
36	1		*REAR TAILGATE STEP PANEL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,815.82	12,566.80
- List Item Discount on L Items 25.00/25.00% (\$)	3,911.46	1,554.20
Total Parts (\$)	19,904.36	11,012.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/REWIRE DAMAGED PORTION	New	250.00	30.00
2	TO REPAIR FRONT RADIO UNIT	New	200.00	0.00
3	TO REPAIR REAR TOP COVER SHELTER	New	400.00	200.00
4	TO DISM/RENEW REAR STICKER	New	120.00	0.00
5	TO DISM/REPAIR REAR EXHAUST PIPE	New	200.00	0.00
6	TO PANEL BEAT DAMAGED PORTION (CHASSIS FRAME) AND RENEW REAR FLOOR BOARD	New	2,800.00	2,000.00
7	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,500.00	1,400.00
8	TO SPRAY UNDERCOATING IN REPAIR	New	280.00	150.00
Gross Labour Cost (\$\$)			5,750.00	3,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >