



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

JTFUF34Y50301969

TP Ergo

Nett: 13K

Xiao Chen

LKK

DATE 19/04/2022 OUR REF: UAPL1523
REPAIR ESTIMATE TO THE TOYOTA DYNA no: GZ5837A

- 1 FRONT L/H DOOR PILLAR ASSY *Distorted*
- 1 FRONT R/H DOOR PILLAR ASSY *Repair*
- 1 FRONT R/H MUDFLAT PLATE *3 rollers*
- 1 FRONT RAIDATOR SPARE TANK *new*
- 2 FRONT RUBBER HOLDING *new*
- 1 FRONT AIR CLEARING HOUSING *new*
- 1 FRONT AIR CLEARING JOINT *Distorted*
- 1 REAR TAILGATE ASSY *Distorted*
- 4 REAR TAILGATE HINGES *Best*
- 1 REAR TAILGATE TOYOTA STICKER *new*
- 1 REAR TAILGATE DYNA STICKET *new*
- 2 REAR TAILGATE LOCK HANDER (LOWER) *3 LH added*
- 2 REAR TAILGATE LOWER LOCK ARM
- 1 REAR TAILGATE LOWER MEMBER *new*
- 2 REAR TAILGATE STOPPER RUBBER *LH missing*
- 2 REAR TAILGATE RUBBER BRACKET *Best LH*
- 2 REAR COMBINATION LAMP ASSY *new*
- 2 REAR COMBINATION LAMP BRACKET *Best*
- 1 REAR NUMBER PLATE BRACKET *Distorted*
- 1 REAR NUMBER PLATE LAMP *new*
- 1 REAR CENTRE CHASSIS CROSSMEMBER *new*
- 1 REAR SPARE WHEEL CARRIER *new*
- 1 REAR EXHAUST PIPE *new*
- 2 REAR MUDFLAT (L and R) *new*
- 1 REAR FLOOR BOARD PANEL *Distorted*
- 1 L/H SIDE GATE PANEL ASSY *Dented*
- 1 R/H SIDE GATE PANEL ASSY *Repair*
- 4 L/H SIDE GATE HINGES *3 new*
- 4 R/H SIDE GATE HINGES *3 new*
- 1 REAR EXHAUST PIPE *3 new*
- 1 REAR EXHAUST MOUNTING

\$	1,233.80	<i>895</i>
\$	1,233.80	<i>x</i>
\$	286.40	<i>x</i>
\$	112.40	<i>x</i>
\$	168.80	<i>x</i>
\$	678.60	<i>396</i>
\$	204.40	<i>✓</i>
\$	1,456.30	<i>✓</i>
\$	157.20	<i>✓</i>
\$	236.80	<i>x</i>
\$	41.20	<i>✓</i>
\$	312.40	<i>89</i>
\$	530.60	<i>198</i>
\$	485.90	<i>x</i>
\$	146.40	<i>35</i>
\$	291.20	<i>145.60</i>
\$	627.60	<i>570</i>
\$	267.80	<i>✓</i>
\$	159.60	<i>✓</i>
\$	48.60	<i>✓</i>
\$	855.62	<i>✓</i>
\$	386.60	<i>x</i>
\$	589.80	<i>x</i>
\$	691.20	<i>x</i>
\$	10000.00	<i>6000</i>
\$	1,553.10	<i>✓</i>
\$	1,553.10	<i>x</i>
\$	157.20	<i>x</i>
\$	157.20	<i>x</i>
\$	779.60	<i>x</i>
\$	42.60	<i>x</i>
\$	20,879.62	
\$	5,219.91	
\$	<u>15,659.72</u>	

LESS 25%.....

6216.80 SN: 6000
4662.60



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/000

SPECIAL NETT:-

- 1 REAR NUMBER PLATE *but*
- 1 REAR TAILGATE (70KM/H) STICKER *3m*
- 1 REAR TAILGATE (13PAX) STICKER *mm*
- 1 SET SIDE AND REAR COMPANY STICKER *mm*
- 1 REAR TAILGATE STEP PANEL *mm*

\$ 30.00 ✓
\$ ~~20.00~~ 10
\$ ~~20.00~~ 10
\$ ~~500.00~~ 300
\$ 100.00 X

350

LABOUR CHARGES:-

- TO DISM/REWIRE DAMAGED PORTION
- TO REPAIR FRONT RADIO UNIT
- TO REPAIR REAR TOP COVER SHELTER
- TO DISM/RENEW REAR STICKER
- TO DISM/REPAIR REAR EXHAUST PIPE
- TO PANEL BEAT DAMAGED PORTION (CHASSIS FRAME) AND RENEW REAR FLOOR BOARD
- TO PUTTY AND RESPRAY DAMAGED PORTION
- TO SPRAY UNDERCOATING IN REPAIR

\$ 250.00 30
\$ 200.00 X
\$ 400.00 200
\$ 120.00 X
\$ 200.00 X 3780
\$ 2,800.00 2000
\$ 1,500.00 1400
\$ ~~280.00~~ 150
\$ 22,079.72

total 14792.60

c/s: 11.8K

10 Days

11.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: