5/20/22, 12:39 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22003388/KQY3N2

Date: 20/05/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No: QAM21A00002700

Claimant Vehicle SHC5135B Insured Vehicle No: SJD7641P

Date of Loss: 11/04/2022 Nature of Claim: TP Claim No: DQAM2200010H/02/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5135B

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2H02481

Reg. Date: 16/10/2020 (Man. Year: 2020) Chassis No: JTDKB3FU203092239

Colour: Metallic Pearl White/Red Odometer: 145114 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm
Front Right Side: Sailun 9 mm
Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 2,818.07 | 971.10 | 1,846.97 | 65.54 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,390.00 | 470.00 | 6,920.00 | 93.64 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 10,208.07 | 1,441.10 | 8,766.97 | 85.88 |
| + GST 7.00/7.00% (S\$) | 714.56 | 100.88 | 613.68 | 85.88 |
| Nett Amount (S\$) | 10,922.63 | 1,541.98 | 9,380.65 | 85.88 |

INSPECTION

Date of Assignment: 12/04/2022

Trans-Cab Services Pte Ltd (HQ)

Date Inspected: 13/04/2022 Inspected At: 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

5/20/22, 12:39 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 May 2022)

Parts: TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for SHC5135B)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--|--------------|-------------------------------------|-------------------|------------|------------|
| 1 | 1 | | *COVER,REAR BUMPER | Buckled | 485.60 FL | *485.60 FL |
| 2 | 1 | | *REINFORCEMENT SUB-ASSY,REAR BUMPER | Bent | 332.70 FL | *332.70 FL |
| 3 | 1 | | *COVER,REAR BUMPER,LOWER | Dented | 22.00 FL | *22.00 FL |
| 4 | 1 | | *GUARD,REAR BUMPER,CENTER | Bent | 374.50 FL | *374.50 FL |
| 5 | 1 | | *RETAINER,REAR BUMPER SIDE,RH | No such part | 132.60 FL | *- FL |
| 6 | 1 | | *REFLECTOR ASSY,REFLEX,RH | Serviceable | 39.00 FL | *- FL |
| 7 | 1 | | *COVER,DECK TRIM,REAR | Serviceable | 126.70 FL | *- FL |
| 8 | 1 | | *PANEL SUB-ASSY,BODY LOWER BACK | Repair | 651.00 FL | *- FL |
| 9 | 1 | | *SET PARKING AID | Serviceable | 700.00 FS | *- FS |
| 10 | 1 | | *SET REAR BUMPER CLIP | Necessary | 95.00 FS | *60.00 FS |
| 11 | 1 | | *REAR SPOILER CLIP | Not Necessary | 70.00 FS | *- FS |
| 12 | 1 | | *REAR BUMPER PROTECTOR | No such part | 180.00 FS | *- FS |
| 13 | 1 | | *SET REAR BUMPER RETAINER CLIP | Not Necessary | 85.00 FS | *- FS |
| 14 | 1 | | *END PANEL TRIM CLIP | Not Necessary | 65.00 FS | *- FS |
| F=Fra | ınchise | part. S=SpcN | lett. L=ListItemDisc. | _ | | |
| | | | | Sub Total (S\$) | 3,359.10 | 1,274.80 |
| | - List Item Discount on L Items 25.00/25.00% (S\$) | | | 541.03 | 303.70 | |
| | | | | Total Parts (S\$) | 2,818.07 | 971.10 |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|--------------|------------|--------|
| Lab | our Items | | | |
| 1 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 2 | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME | New | 2,200.00 | 200.00 |
| 3 | TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 4 | TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 180.00 | 0.00 |
| 5 | TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR | New | 480.00 | 0.00 |
| 6 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 7 | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS | New | 250.00 | 0.00 |
| 8 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 2,200.00 | 220.00 |
| 9 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 50.00 |
| 10 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 0.00 |
| 11 | TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 12 | TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS | New | 380.00 | 0.00 |
| | Gross Labou | r Cost (S\$) | 7,390.00 | 470.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >