

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22003393/ANY3Q2**Date:** 15/08/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SLU8483J **Insured Vehicle No :** SNE2810Z

Date of Loss: 08/04/2022 Nature of Claim: TP Claim No: DMCF2200010H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8483J**

Make & Model: BMW 118I, 1.5 MSPT LED HL LED FL (A) Engine No: 2ZR0A36564

Reg. Date: 15/12/2017 (Man. Year: 2017) Chassis No: ZVW400027507

Colour: Silver Odometer: 304640 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,126.50	4,300.85	2,825.65	39.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,940.00	2,010.00	50.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,076.50</b>	<b>6,240.85</b>	<b>4,835.65</b>	<b>43.66</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,000.00</b>		
<b>(\$\$)</b>	11,076.50	5,000.00	6,076.50	54.86
<b>+ GST 7.00/7.00% (\$\$)</b>	775.36	350.00	425.36	54.86
<b>Nett Amount (\$\$)</b>	<b>11,851.86</b>	<b>5,350.00</b>	<b>6,501.86</b>	<b>54.86</b>

INSPECTION

Date of Assignment: 12/04/2022

Date Inspected: 13/04/2022 Inspected At:

MG SOLUTION PTE LTD  
23 KAKI BUKIT AVE 4 (SOUTH WING)  
#02-03B VICOM INSPECTION CENTRE,  
SINGAPORE 415933

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2022)
<b>Parts:</b>	143	BMW 118I 1.5 MSPT LED HL LED FL (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU8483J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,455.90 FL	*1,177.00 FL
2	1		*TAILGATE LOGO	Not Necessary	72.10 FL	*- FL
3	1		*TAILGATE EMBLEM PRIUS	Necessary	68.00 FL	*68.00 FL
4	1		*TAILGATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	60.00 FL	*60.00 FL
5	2		*TAILGATE DAMPER	Not Necessary	560.00 FL	*- FL
6	2		*TAILGATE HINGE	Not Necessary	120.00 FL	*- FL
7	1		*TAILGATE LOCK	Damaged	360.00 FL	*360.00 FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	80.00 FL	*- FL
9	1		*TAILGATE INNER BOARD	Cracked	530.00 FL	*530.00 FL
10	1		*TAILGATE INNER HANDLE	Not Necessary	60.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIPE	Cut	320.00 FL	*320.00 FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	155.60 FL	*155.60 FL
13	1		*TAILGATE NUMBER PLATE OUTER GARNISH	Not Necessary	420.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	820.00 FL	*820.00 FL
15	1		*REAR BUMPER SIDE RETAINER	O/S Damaged	144.80 FL	*72.40 FL
16	1		*REAR BUMPER REFLECTOR	Cracked	90.00 FL	*90.00 FL
17	1		*TAILLAMP RH	Cracked	689.00 FL	*689.00 FL
18	1		*REAR FENDER INNER TRIM(LOWER) RH	Not Necessary	888.50 FL	*- FL
19	1		*REAR END PANEL	Dented	630.00 FL	*630.00 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	255.80 FL	*255.80 FL
21	1		*REAR EXHAUST PIPE	Not Necessary	922.30 FL	*- FL
22	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
23	1		*SET TAILGATE INNER BOARD CLIPS	Necessary	20.00 FS	*20.00 FS
24	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
26	1		*REAR END PANEL INSULATOR SEAL	Necessary	150.00 FS	*60.00 FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
28	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,302.00</b>	<b>5,607.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,175.50	1,306.95
<b>Total Parts (\$)</b>	<b>7,126.50</b>	<b>4,300.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
7	TRANSFER TAILGATE MECHANISM	New	120.00	80.00
8	REMOVE AND REFIX REAR WINDSCREEN	New	160.00	120.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	220.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,950.00</b>	<b>1,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >