

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003395/UQY3N2**Date:** 04/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00116092100
Claimant Vehicle No :	SMC6656Z	Insured Vehicle No :	SBP8888U
Date of Loss:	11/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202487/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6656Z	Engine No:	03477775N55B30A
Make & Model:	BMW 535I, 3.0 (A)	Chassis No:	WBAFR72090C581242
Reg. Date:	23/09/2011 (Man. Year: 2011)	Odometer:	172597 km
Colour:	Grey		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35R20	Rear Tyre Size:	275/30R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,550.50	4,507.93	6,042.57	57.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,180.00	1,120.00	48.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,850.50	5,687.93	7,162.57	55.74
Approved Total (Overridden) (\$\$)		4,550.00		
Nett Amount (\$\$)	12,850.50	4,550.00	8,300.50	64.59

INSPECTION

Date of Assignment:	16/04/2022	
Date Inspected:	12/04/2022	Inspected At: Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2022)
Parts:	143	BMW 535I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC6656Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,658.00 FL	*- FL
2	1		*REAR BOOT LOGO	Not Necessary	79.00 FL	*- FL
3	1		*REAR BUMPER PDC SENSOR (4 Pcs)	Shorted (2 Pcs only)	1,476.00 FL	*450.00 FL
4	1		*REAR BUMPER UNDERCOVER	Cracked	176.50 FL	*176.50 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	685.00 FL	*685.00 FL
6	1		*REAR END PANEL	Repair	923.40 FL	*- FL
7	1		*REAR BUMPER TOP RETAINER	Cracked	340.00 FL	*261.23 FL
8	1		*REAR BUMPER INNER FRAME GARNISH	Cracked	289.00 FL	*289.00 FL
9	1		*REAR BUMPER SIDE HOLDERS	N/s Cracked	278.60 FL	*139.30 FL
10	1		*REAR TAILLAMPS	N/s Cracked	1,682.40 FL	*681.00 FL
11	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
12	1		*REAR M SPORT BUMPER	Distorted	2,300.00 FS	*1,600.00 FS
13	1		*REAR M SPORT BUMPER LOWER LID	Distorted	680.00 FS	*300.00 FS
14	1		*REAR BUMPER TOWING COVER	Not Necessary	42.00 FS	*- FS
15	1		*REAR BUMPER REFLECTOR	Not Necessary	260.00 FS	*- FS
					Sub Total (\$\$)	10,929.90
					- List Item Discount on L Items 5.00/5.00% (\$\$)	379.40
					Total Parts (\$\$)	10,550.50
						4,642.03
						134.10
						4,507.93

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	500.00
2	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,000.00	600.00
3	TO APPLY UNDERCOATING	New	100.00	0.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE,REPLACE DAMAGED LAMP AND CHECK REAR WIRING	New	100.00	30.00
Gross Labour Cost (\$)			2,300.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >