5/13/22, 9:18 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003396/UTY3N2

13/05/2022 Date:

Engine No:

Chassis No:

Odometer:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00089802101

Claimant Vehicle

SJX7273M

Insured Vehicle No:

XD7162P

No: Date of Loss:

08/04/2022

Nature of

Claim:

TP

Claim SNM22D202443/C02/THAMYL

R16B25100418

184268 km

MRHFB1630FP000194

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJX7273M Reg No:

Make & Model: HONDA CIVIC, 1.5 (A)

Reg. Date: 09/12/2015 (Man. Year: 2015)

Colour: Grey

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16 Front Left Side: Rear Left Side: Continental 6 mm West Lake 6 mm Front Right Side: Rear Right Side: Continental 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 4,161.60 | 3,084.96 | 1,076.64 | 25.87 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,000.00 | 2,130.00 | 870.00 | 29.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,161.60 | 5,214.96 | 1,946.64 | 27.18 |
| Approved Total (Overridden) (S\$) | | 4,150.00 | | |
| (S\$) | 7,161.60 | 4,150.00 | 3,011.60 | 42.05 |
| + GST 7.00/7.00% (S\$) | 501.31 | 290.50 | 210.81 | 42.05 |
| Nett Amount (S\$) | 7,662.91 | 4,440.50 | 3,222.41 | 42.05 |

INSPECTION

Date of Assignment: 16/04/2022

SHIN AUTOMOBILE & TRADING PTE LTD (HQ) 13/04/2022 Inspected At: Date Inspected:

15 Kaki Bukit Rd 4, #01-46 BARTLY BIZ CENTRE

Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 May 2022)

Parts: 143 HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX7273M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--|--------------|---------------------------------|-------------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Distorted | 638.20 FL | *638.20 FL |
| 2 | 1 | | *REAR RH FENDER | Badly Dented | 852.40 FL | *852.40 FL |
| 3 | 1 | | *REAR RH FENDER AIR VENT | Cracked | 56.00 FL | *56.00 FL |
| 4 | 1 | | *REAR WINDSCREEN MOULDING | Necessary | 49.90 FL | *49.90 FL |
| 5 | 1 | | *REAR RH DOOR | Badly Dented | 890.70 FL | *890.70 FL |
| 6 | 1 | | *REAR RH DOOR FRAME STICKER | Necessary | 59.40 FL | *59.40 FL |
| 7 | 1 | | *REAR TAILLAMP | Not Necessary | 308.20 FL | *- FL |
| 8 | 1 | | *REAR BUMPER LOWER SPOILER | Cut / Deformed | 900.00 FS | *900.00 FS |
| 9 | 1 | | *REAR BUMPER SIDE RETAINER | O/s Cracked | 69.20 FL | *34.60 FL |
| 10 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 80.00 FS | *40.00 FS |
| 11 | 1 | | *SET REAR RH FENDER SEALANT | Not Necessary | 80.00 FS | *- FS |
| 12 | 1 | | *SET REAR RH DOOR SEALANT | Not Necessary | 80.00 FS | *-FS |
| 13 | 1 | | *SET REAR WINDSCREEN SEALANT | Necessary | 60.00 FS | *40.00 FS |
| 14 | 1 | | *SET REAR WINDSCREEN INNER SEAL | Necessary | 50.00 FS | *40.00 FS |
| 15 | 1 | | *BTL REAR WINDSCREEN PRIMER | Not Necessary | 80.00 FS | *- FS |
| 16 | 1 | | *SET REVERSE SENSOR | Not Necessary | 200.00 FS | *-FS |
| F=Fra | anchise | part. S=SpcN | ett. L=ListItemDisc. | _ | | |
| | | | | Sub Total (S\$) | 4,454.00 | 3,601.20 |
| | - List Item Discount on L Items 10.00/20.00% (S\$) | | | | 292.40 | 516.24 |
| | | | | Total Parts (S\$) | 4,161.60 | 3,084.96 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|------------|------------|----------|
| Lab | our Items | | | |
| 1 | TO CHECK WIRING SYSTEM. | New | 50.00 | 20.00 |
| 2 | TO TRANSFER REAR BUMPER SENSOR ATTACHMENT. | New | 100.00 | 50.00 |
| 3 | TO R&R REAR INNER TRIM FOR HOT WORK REPAIR. | New | 200.00 | 80.00 |
| 4 | TO CARRY OUT BODY CAVITY PRESERVATION. | New | 200.00 | 60.00 |
| 5 | TO RESER AND REPROGRAMME AFTER REPAIR THE VEHICLE. | New | 200.00 | 50.00 |
| 6 | TO R&R REAR WINDSCREEN GLASS. | New | 150.00 | 120.00 |
| 7 | TO TRANSFER REAR RH DOOR ATTACHMENTS. | New | 100.00 | 50.00 |
| 8 | TO CUT & WEILD ON REAR RH FENDER. TO PANEL BEAT ON REAR RH FENDER INNER PANEL. TO R&R REAR RH DOOR, REAR BUMPER AND OTHER ATTACHMENTS. | New | 1,000.00 | 800.00 |
| 9 | TO RESPRAY ON REAR BUMPER, REAR RH FENDER, REAR RH DOOR AND ACCIDENT AFFECTED AREA. | New | 1,000.00 | 900.00 |
| | Gross Labour Cost | | 3,000.00 | 2,130.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >