

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003398/ANY3M4**Date:** 15/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00130412102

**Claimant Vehicle No :** GBL5231E **Insured Vehicle No :** SLD2628M

Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: SNM22D202278/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBL5231E**

Make & Model: BYD T3, (A) Engine No: HIDDEN

Reg. Date: 06/09/2021 (Man. Year: 2021) Chassis No: LC0CE4DB6M0020766

Colour: White Odometer: 14600 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/60R16C Rear Tyre Size: 195/60R16C

Front Left Side: Linglong 6 mm Rear Left Side: Linglong 6 mm

Front Right Side: Linglong 6 mm Rear Right Side: Linglong 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,784.48	2,977.85	1,806.63	37.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,290.00	1,000.00	43.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,074.48</b>	<b>4,267.85</b>	<b>2,806.63</b>	<b>39.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>(S\$)</b>	7,074.48	3,400.00	3,674.48	51.94
<b>+ GST 7.00/7.00% (S\$)</b>	495.21	238.00	257.21	51.94
<b>Nett Amount (S\$)</b>	<b>7,569.69</b>	<b>3,638.00</b>	<b>3,931.69</b>	<b>51.94</b>

**INSPECTION**

Date of Assignment: 12/04/2022

Date Inspected: 13/04/2022 Inspected At: KAI MOTOR TRADING (HQ)  
BLK 3007 UBI ROAD 1, #01-440  
Singapore 408701

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
Parts:	M1-MPV	BYD T3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5231E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Buckled	1,892.00 FL	*1,892.00 FL
2	1		*REAR LAMP RH	Not Necessary	563.50 FL	*- FL
3	1		*REAR AIR GARNISH	Cracked	146.35 FL	*146.35 FL
4	1		*REAR BUMPER	Deformed	874.30 FL	*874.30 FL
5	1		*REAR BUMPER BRACKET	Damaged	119.60 FL	*59.80 FL
			2PCS X \$59.80			
6	1		*REAR BUMPER SIDE RETAINER	O/s Necessary	117.00 FL	*58.50 FL
			2PCS X \$58.50			
7	1		*RETAINING PLATE ASSY	Not Necessary	558.90 FL	*- FL
8	1		*REAR DOOR LOCK ASSY	Not Necessary	373.00 FL	*- FL
9	1		*VENT SIDEWALL PLATE RH	Not Necessary	49.60 FL	*- FL
10	1		*TRIM PANEL ASSY, GUIDE RAIL RH	Not Necessary	177.40 FL	*- FL
11	1		*REVERSE SENSOR	Damaged	400.00 FS	*250.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	5,271.65 3,280.95
					- List Item Discount on L Items 10.00/10.00% (\$\$)	487.17 303.10
					Total Parts (\$\$)	4,784.48 2,977.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY	New	950.00	600.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,100.00	600.00
3	TO REMOVE UPHOLSTERY	New	120.00	60.00
4	TO CHECK WIRING FUNCTIONS	New	120.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,290.00</b>	<b>1,290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >