

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003410/RQCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant: CHIA CHIN SIONG Policy No: 7210000310
Date of Loss: 08/04/2022 Nature of Claim: OD Claim No: 9941788663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX5465D**
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC22980
Reg. Date: 19/01/2021 (Man. Year: 2020) Chassis No: WAUZZZF33M1060290
Colour: White Odometer: 28530 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$166,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,386.00	16,208.16	16,177.84	49.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,472.00	8,132.00	6,340.00	43.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,858.00	24,340.16	22,517.84	48.06
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	46,058.00	23,540.16	22,517.84	48.89
+ GST 7.00/7.00% (S\$)	3,224.06	1,647.81	1,576.25	48.89
Nett Amount (S\$)	49,282.06	25,187.97	24,094.09	48.89

INSPECTION

Date of Assignment: 13/04/2022
Date Inspected: 12/04/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 9.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Scratched	162.00 FS	*129.20 FS
3	2		*FRONT BUMPER CLOSING ELEMENT LH / RH	Not Necessary	132.00 FS	*- FS
4	1		*FRONT BUMPER CENTRE GRILLE	Cracked	242.00 FS	*193.60 FS
5	1		*FRONT BUMPER LOWER COVER	Not Necessary	58.00 FS	*- FS
6	2		*FRONT BUMPER GRILLE LH / RH	Not Necessary	248.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Scratched	426.00 FS	*340.80 FS
9	2		*AIR GUIDE GRILLE LH / RH	Not Necessary	342.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,594.00 FS	*1,275.20 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	271.00 FS	*216.80 FS
12	1		*RADIATOR GRILLE CAP COVER	Not Necessary	47.00 FS	*- FS
13	1		*RADIATOR GRILLE BRACKET	Not Necessary	46.00 FS	*- FS
14	1		*FRONT CAMERA	Not Necessary	1,261.00 FS	*- FS
15	1		*FRONT BUMPER FOAM	Not Necessary	114.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	974.00 FS	*778.80 FS
17	2		*FRONT BUMPER GUIDE SECTION LH / RH	Not Necessary	86.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Cracked	137.00 FS	*109.60 FS
19	1		*SIGN CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
20	1		*AIR CON STICKER	Necessary	9.00 FS	*6.64 FS
21	2		*FRONT SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
22	4		*FRONT SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
23	1		*SET FRONT BUMPER WIRING	Not Necessary	750.00 FS	*- FS
24	1		*SIGNAL HORN HIGH TONE LH	Not Necessary	153.00 FS	*- FS
25	1		*SIGNAL HORN LOW TONE RH	Not Necessary	145.00 FS	*- FS
26	2		*SPRING SHACKLE LH / RH	Not Necessary	50.00 FS	*- FS
27	1		*BONNET	Bent	3,695.00 FS	*2,956.00 FS
28	2		*BONNET HINGE LH / RH	Bent	162.00 FS	*128.96 FS
29	1		*BONNET ATTACHMENTS PARTS	Not Necessary	309.00 FS	*- FS
30	2		*BONNET STRIKER LH / RH	Bent	246.00 FS	*196.00 FS
31	1		*SOUND ABSORBER FOR ENGINE BONNET	Not Necessary	244.00 FS	*- FS
32	1		*IMPACT PROTECTION CENTRE	Cracked	31.00 FS	*24.24 FS
33	2		*BONNET COVER LH / RH	Not Necessary	92.00 FS	*- FS
34	1		*PLENUM CHAMBER COVER	Cut	144.00 FS	*114.80 FS
35	1		*BOWDEN CABLE CENTER	Torn	64.00 FS	*50.56 FS
36	1		*BONNET RELEASE LEVER	Cut	16.00 FS	*12.64 FS
37	1		*BONNET COVER	Not Necessary	11.00 FS	*- FS
38	1		*BONNET LID LOCK CABLE	Not Necessary	82.00 FS	*- FS
39	1		*BONNET RELEASE ELEMENT	Bent	65.00 FS	*51.44 FS
40	2		*BONNET LID LOCK	Bent	455.00 FS	*364.00 FS
41	1		*WHEEL HOUSING LINER FRONT LH	Not Necessary	260.00 FS	*- FS
42	1		*WHEEL HOUSING LINER FRONT RH	Not Necessary	260.00 FS	*- FS
43	1		*WHEEL HOUSING LINER ATTACHMENTS FRONT / REAR	Not Necessary	105.00 FS	*- FS
44	2		*FRONT FENDER COVER LH / RH	Not Necessary	36.00 FS	*- FS
45	2		*HEADLIGHT MOUNTING LH / RH	Broken	264.00 FS	*210.40 FS
46	1		*LED HEADLIGHT	N/S Cracked / O/SNot Necessary	11,904.00 FS	*4,761.60 FS
47	2		*LED HEADLIGHT LIFT CYLINDER LH / RH	Not Necessary	462.00 FS	*- FS
48	1		*LIFT CYLINDER HOSE RH	Torn	92.00 FS	*73.44 FS
49	1		*LOCK CARRIER MOUNTING	Cracked	1,412.00 FS	*1,129.60 FS
50	1		*AC CONDENSER	Bent	605.00 FS	*483.60 FS
51	6		*COOLANT	Necessary	282.00 FS	*225.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
52	1		*RADIATOR AIR GUIDE LH / RH	N/S Broken/O/S Not Necessary	86.00 FS	*34.08 FS	
53	1		*RADIATOR AIR GUIDE UPPER / LOWER	UpperBroken/LowerNot Necessary	96.00 FS	*37.84 FS	
54	1		*COVER	Not Necessary	30.00 FS	*- FS	
55	1		*AIR GUIDE INNER	Broken	59.00 FS	*46.48 FS	
56	1		*AIR GUIDE OUTER	Not Necessary	21.00 FS	*- FS	
57	1		*AIR GUIDE CENTRE	Not Necessary	35.00 FS	*- FS	
58	2		*WHEEL COVER FRONT RH / LH	Necessary	566.00 FS	*452.00 FS	
59	2		*WATER DEFLECTOR STRIP LH / RH	Not Necessary	104.00 FS	*- FS	
60	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS	
61	1		*SUNDRIES	Necessary	400.00 FS	*15.04 FS	
					Total Parts (S\$)	32,386.00	16,208.16

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,700.00	1,700.00
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGE AND BOTH FRONT FENDERS	New	4,500.00	1,810.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	14,472.00
				8,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >