



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 8540T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT L/H FENDER (N)	DENTED	1,955.00	893.00
1	FRONT L/H HEADLAMP (N)	CUT	2,150.00	2,150.00
1	FRONT BUMPER (N)	DEFORMED	2,050.00	1,466.00
2	FRONT BUMPER SENSOR @\$210.00 (N)	NOT NECESSARY	420.00	-
10	FRONT BUMPER CLIPS @\$5.00 (N)	NECESSARY	50.00	50.00
1	FRONT BUMPER SIDE RETAINER -LH (N)	NOT NECESSARY	258.00	-
	LESS 10% DISCOUNT		-	-455.90
			6,883.00	4,103.10
	<u>LABOUR</u>			
	TO REMOVE & REFIX FRONT SENSOR.		120.00	50.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TUFF KOTE.		120.00	30.00
	PANEL BEATING.		600.00	400.00
	SPRAY PAINTING.		600.00	400.00
			1,520.00	910.00
	GRAND TOTAL		8,403.00	5,013.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS/SMO22003413/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.