

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22003414/KVY3E2

Date: 17/06/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962467		
Claimant Vehicle No :	SMZ9009B	Insured Vehicle No :	SMR859R		
Date of Loss:	04/04/2022	Nature of Claim:	TP	Claim No:	272301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ9009B	Engine No:	1NZR410744
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Chassis No:	NHP1707048063
Reg. Date:	05/08/2016 (Man. Year: 2016)	Odometer:	114778 km
Colour:	Metallic Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 2 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 2 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,215.65	2,215.65	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	580.00	300.00	34.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,095.65	2,795.65	300.00	9.69
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	3,095.65	2,200.00	895.65	28.93
+ GST 7.00/7.00% (S\$)	216.70	154.00	62.70	28.93
Nett Amount (S\$)	3,312.35	2,354.00	958.35	28.93

INSPECTION

Date of Assignment:	13/04/2022	
Date Inspected:	13/04/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ9009B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Damaged / Warped	1,236.00 FL	*1,236.00 FL
2	1		*FRONT LH DOOR LOWER MOULDING	Cut / Dented	129.80 FL	*129.80 FL
3	1		*FRONT LH SIDE MIRROR	Cracked	1,228.40 FL	*1,228.40 FL
4	1		*FRONT LH DOOR FRAME STICKER	Necessary	120.00 FS	*120.00 FS
5	1		*FRONT LH DOOR SUN VISOR	Necessary	150.00 FS	*150.00 FS
					Sub Total (\$\$)	2,864.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	648.55
					Total Parts (\$\$)	2,215.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	450.00	250.00
2	PUTTY & RESPRAY	New	400.00	300.00
3	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			880.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >