

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22003416/Rqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 12/05/2022 SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 2638L **GBK 9425S** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03YBO Excess (\$) 0.00 **LOH CYNTHIA Assign Date** 13/04/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE VAN TURBO Make & Model 2982 C.C 5DR MT Engine No. **HIDDEN** Year of Reg. 2021 Chassis No. JTFHT02PX00251278 Colour **GREY** 48862 KM Odometer **IN ORDER** Steering **IN ORDER** NIL **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 195R15C MICHELIN 6 mm R/H Front Tyre MICHELIN L/H Front Tyre 195R15C 6 mm R/H Rear Tyre 195R15C **MICHELIN** 6 mm 195R15C **MICHELIN** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. 5. **General Information Accident Date** 09/04/2022 **Inspect Date / Time** 13/04/2022 (02:34 PM) MJE MOTOR Survey held at BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/ASM22003416/Rqy3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE

ESTIMATED NORMAL PERIOD FOR REPAIR:

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser