

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile								
	LONPAC INSURAN	NCE BHD	Ref:	CC4/LPC22003419/Upa3q2				
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	21/06/2022				
			Code:	LPC2				
1.	Po	Policy Particulars :- THIRD PARTY CLAIM (FOR MANDATE ONLY)						
	Insured Veh.	YN 4646R	Veh. Inspected	GBC 9485K				
	Policy No.	Z21VC05007627	Coverage (\$)	0.00				
	Claim No.	21/22/22/VC05/025654	Excess (\$)	0.00				
	Assign From		Assign Date	13/04/2022				
2.		Vehicle Partic	culars & Condition					
	Make & Model	NISSAN NV350 (M)	c.c	2488				
	Engine No.	HIDDEN	Year of Reg.	2014				
	Chassis No.	JN1MC2E26Z0001622	Colour	SILVER				
	Odometer	321375 KM	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	NIL				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	195 R15	MICHELIN	6 mm				
	L/H Front Tyre	195 R15	MICHELIN	6 mm				
	R/H Rear Tyre	195 R15	MICHELIN	6 mm				
	L/H Rear Tyre	195 R15	MICHELIN	6 mm				
4.	Description of Damages							
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.							
	DAMAGES SEE DETAILS.							
5.		General	Information					
	Accident Date	06/04/2022	Inspection Date	13/04/2022				
	Survey held at	FASTECH AUTO PTE LTD						
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. C)FOR MANDATE ONLY.							
5b.		Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 9485K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILLAMP O/S	BROKEN	224.80	224.80
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	2,010.30	-
1	REAR BUMPER	NOT NECESSARY	894.20	-
	LESS 10% DISCOUNT		-	-22.48
			3,129.30	202.32
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING.		50.00	20.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S .		680.00	480.00
	TO PUTTY & SPRAY PAINTING.		900.00	300.00
			1,680.00	820.00
	GRAND TOTAL		4,809.30	1,022.32

RECOMMENDED COST OF REPAIRS		1,022.32
(FOR MANDATE ONLY)		·

Report Ref No. CC4/LPC22003419/Upa3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 9485K

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 9485K

RE-INSPECTION











