

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003420/KQY3M4**Date:** 29/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00006312200

Claimant Vehicle No : SKV3807Z **Insured Vehicle No :** GBA5353U

Date of Loss: 12/04/2022 Nature of Claim: TP Claim No: SNM22D202494C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV3807Z**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRY218984

Reg. Date: 15/09/2015 (Man. Year: 2015) Chassis No: MR053REH104540310

Colour: Metallic Pearl White Odometer: 95741 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,954.07	3,233.25	720.82	18.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	690.00	770.00	52.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,414.07	3,923.25	1,490.82	27.54
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	5,414.07	3,100.00	2,314.07	42.74
+ GST 7.00/7.00% (S\$)	378.98	217.00	161.98	42.74
Nett Amount (S\$)	5,793.05	3,317.00	2,476.05	42.74

INSPECTION

Date of Assignment: 30/06/2022

Date Inspected: 05/05/2022 Inspected At: 160 SIN MING DRIVE #03-18/19
SIN MING AUTOCITY SINGAPORE 575722
REPAIRER: EM SOLUTION PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV3807Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Bent	1,349.00 FL	*1,247.20 FL
2	1		*FRT DOOR WING MIRROR RH	Cracked/Dented	771.30 FL	*771.30 FL
3	1		*FRT DOOR HINGE. TOP & LOWER	Repair	206.00 FL	*- FL
4	1		*FRT DOOR WINDOW CHROME MOULDING RH	Dented	146.20 FL	*146.20 FL
5	1		*FRT DOOR REGULATOR GEAR RH	Bent	336.10 FL	*317.20 FL
6	1		*FRT DOOR REGULATOR GEAR MOTOR RH	Jammed	979.50 FL	*926.10 FL
7	1		*FRT DOOR INNER TRIM BOARD RH	Mtg Cracked	1,015.60 FL	*903.00 FL
8	1		*FRONT DOOR OUTER HANDLE RH	Serviceable	468.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,272.10	4,311.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,318.03	1,077.75
Total Parts (\$\$)	3,954.07	3,233.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE, TRANSFER FRT DOOR COMPONENTS	New	100.00	60.00
3	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	200.00
4	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	600.00	380.00
5	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	30.00
Gross Labour Cost (\$)			1,460.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >