

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003423/ANY3Q2**Date:** 18/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: 60204845

Claimant Vehicle No : SKV7633G **Insured Vehicle No :** XE6864Z

Date of Loss: 12/04/2022 Nature of Claim: TP Claim No: SNM22D202522/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV7633G**

Make & Model: MERCEDES-BENZ E200 (R17), 2.0 (A) Engine No: 27186030448798

Reg. Date: 08/10/2012 (Man. Year: 2012) Chassis No: WDD2120482A618746

Colour: Grey Odometer: 189750 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R19 Rear Tyre Size: 225/50 R19

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,623.40	9,948.30	16,675.10	62.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,590.00	1,950.00	5,640.00	74.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,213.40	11,898.30	22,315.10	65.22
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	34,213.40	9,500.00	24,713.40	72.23

INSPECTION

Date of Assignment: 21/07/2022

Date Inspected: 13/04/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2022)
Parts:	143	MERCEDES-BENZ E200 (R17) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV7633G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Distorted	1,944.00 FL	*1,944.00 FL
2	1		*REAR DOOR MOULDING RH (CHROME)	Deformed	185.00 FL	*185.00 FL
3	1		*REAR DOOR OUTER STRIP RH	Necessary	276.00 FL	*276.00 FL
4	1		*REAR DOOR WEATHERSTRIP RH	Necessary	347.00 FL	*347.00 FL
5	1		*REAR DOOR FRAME WEATHERSTRIP RH	Not Necessary	325.00 FL	*- FL
6	1		*REAR DOOR INNER LOCK RH	Damaged	576.00 FL	*366.00 FL
7	1		*REAR DOOR INNER TRIM BOARD RH	Cracked	956.00 FL	*956.00 FL
8	1		*REAR FENDER RH	Distorted	2,640.00 FL	*2,014.00 FL
9	1		*REAR FENDER INNER COWLING RH	Deformed	385.00 FL	*241.00 FL
10	1		*REAR FENDER AIR VENT RH	Not Necessary	138.00 FL	*- FL
11	1		*REAR WINDSCREEN GLASS C/W MOULDING RH	Necessary	1,980.00 FL	*250.00 FL
12	1		*TAIL LAMP RH	Not Necessary	620.00 FL	*- FL
13	1		*TAIL LAMP PANEL RH	Not Necessary	392.00 FL	*- FL
14	1		*REAR BUMPER	Not Necessary	2,185.00 FL	*- FL
15	1		*REAR BUMPER MOULDING (CENTER)	Not Necessary	156.00 FL	*- FL
16	2		*REAR BUMPER MOULDING (SIDE)	Not Necessary	390.00 FL	*- FL
17	2		*REVERSE SENSOR	Not Necessary	552.00 FL	*- FL
18	2		*REVERSE SENSOR HOLDER	Not Necessary	128.00 FL	*- FL
19	1		*REAR ABS SENSOR	Not Necessary	460.00 FL	*- FL
20	1		*REAR CROSSMEMBER	Not Necessary	2,687.00 FL	*- FL
21	1		*REAR SHOCK ABSORBER RH	Not Necessary	780.00 FL	*- FL
22	1		*REAR LOWER ARM RH	Bent	565.00 FL	*565.00 FL
23	1		*REAR KNUCKLE ARM RH	Damaged	1,767.00 FL	*1,190.00 FL
24	1		*REAR WHEEL HUB WITH BEARING RH	Damaged	760.00 FL	*760.00 FL
25	1		*REAR UPPER ARM RH	Damaged	710.00 FL	*198.00 FL
26	1		*REAR ADJUSTABLE ARM RH	Bent	660.00 FL	*240.00 FL
27	1		*REAR CONTROL ARM RH	Bent	675.00 FL	*255.00 FL
28	1		*REAR LINKAGE RH	Not Necessary	210.00 FL	*- FL
29	1		*REAR DRIVESHAFT	Not Necessary	2,477.00 FL	*- FL
30	1		*SET REAR DOOR INNER TRIM BOARD CLIP	Necessary	80.00 FS	*50.00 FS
31	1		*REAR FENDER SEALANT RH	Necessary	80.00 FS	*60.00 FS
32	1		*SET REAR FENDER INNER COWLING RH	Necessary	80.00 FS	*30.00 FS
33	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
35	1		*TAILLAMP PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
36	1		*SET REAR BUMPER CLIP	Not Necessary	150.00 FS	*- FS
37	1		*REAR WHEEL SPORT RIM RH	Dented	1,800.00 FS	*900.00 FS
38	1		*REAR WHEEL TYRE RH	Not Necessary	850.00 FS	*- FS
39	1		*BRAKE OIL	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					29,216.00	10,927.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,592.60	978.70
Total Parts (\$\$)					26,623.40	9,948.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	500.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	250.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	650.00	80.00
7	TRANSFER REAR DOOR MECHANISM	New	150.00	100.00
8	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
9	REMOVE & REFIX REAR SENSOR	New	250.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	850.00	0.00
12	REMOVE AND REFIX REAR UNDERCARRIAGE	New	1,200.00	180.00
Gross Labour Cost (\$\$)			7,590.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >