

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003425/VNY3Q2**Date:** 12/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00118572101
Claimant Vehicle No :	SNE5354D	Insured Vehicle No :	SLX3324C
Date of Loss:	08/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202460/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE5354D		
Make & Model:	MERCEDES-BENZ C180, 1.5 AVANTGARDE LN (A)	Engine No:	27491030388218
Reg. Date:	25/05/2015 (Man. Year: 2015)	Chassis No:	WDD2050402R073082
Colour:	White	Odometer:	0 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,448.14	9,338.04	5,110.10	35.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,370.00	2,270.00	62.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,088.14	10,708.04	7,380.10	40.80
Approved Total (Overridden) (\$\$)		8,450.00		
(\$\$)	18,088.14	8,450.00	9,638.14	53.28
+ GST 7.00/7.00% (\$\$)	1,266.17	591.50	674.67	53.28
Nett Amount (\$\$)	19,354.31	9,041.50	10,312.81	53.28

INSPECTION

Date of Assignment:	26/04/2022	
Date Inspected:	13/04/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2022)

Parts: 143 MERCEDES-BENZ C180 1.5 AVANTGARDE LN (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE5354D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,142.75 FL	*2,142.75 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	57.69 FL	*57.69 FL
3	1		*BOOTLID LOCK	Serviceable	278.50 FL	*- FL
4	1		*BOOTLID LOCK CATCH	Serviceable	105.00 FL	*- FL
5	1		*BOOTLID WEATHERSTRIP	Cut	215.70 FL	*215.70 FL
6	1		*REAR BUMPER	Cut	1,675.44 FL	*1,675.44 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
8	1		*REAR BUMPER LOWER GARNISH	Scratched	332.10 FL	*332.10 FL
9	1		*REAR BUMPER TOWING COVER	Serviceable	55.60 FL	*- FL
10	1		*REAR BUMPER LOWER GARNISH LH CORNER REVERSE SENSOR	Cut	188.10 FL	*188.10 FL
11	1		*REAR BUMPER LOWER GARNISH LH SIDE REVERSE SENSOR	Cut	188.10 FL	*188.10 FL
12	1		*REAR BUMPER LOWER GARNISH CENTRE LH REVERSE SENSOR	Cut	188.10 FL	*188.10 FL
13	1		*REAR BUMPER LOWER GARNISH CENTRE RH REVERSE SENSOR	Cut	188.10 FL	*188.10 FL
14	1		*REAR BUMPER LOWER GARNISH REVERSE SENSOR WIRE HARNESS	Serviceable	425.00 FL	*- FL
15	6		*REAR BUMPER REVERSE SENSOR O-SEAL	Necessary	40.80 FL	*40.80 FL
16	1		*REAR BUMPER CENTRE BRACKET	Cut	167.30 FL	*167.30 FL
17	1		*REAR BUMPER RH SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
18	1		*REAR BUMPER LH SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
19	1		*REAR BUMPER RH BRACKET	Cut	74.00 FL	*74.00 FL
20	1		*REAR BUMPER LH BRACKET	Serviceable	74.00 FL	*- FL
21	1		*REAR BUMPER RH LOWER BRACKET	Cut	47.70 FL	*47.70 FL
22	1		*REAR BUMPER LH LOWER BRACKET	Serviceable	47.70 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Dented	710.20 FL	*710.20 FL
24	1		*REAR BUMPER KICK SENSOR	Serviceable	167.00 FL	*- FL
25	1		*REAR BUMPER KICK SENSOR GARNISH COVER	Cut	118.20 FL	*118.20 FL
26	1		*REAR BUMPER KICK SENSOR CONTROL UNIT	Serviceable	373.30 FL	*- FL
27	1		*REAR BUMPER LOWER LH COVER	Cut	173.00 FL	*173.00 FL
28	1		*RH TAILLAMP ASSY	Cracked	766.80 FL	*766.80 FL
29	1		*RH TAILLAMP LOWER BRACKET	Cut	76.00 FL	*76.00 FL
30	1		*LH TAILLAMP ASSY	Cracked	766.80 FL	*766.80 FL
31	1		*LH TAILLAMP LOWER BRACKET	Serviceable	76.00 FL	*- FL
32	1		*END PANEL	Dented	1,532.00 FL	*1,532.00 FL
33	1		*END PANEL INNER GARNISH	Cut	188.50 FL	*188.50 FL
34	1		*SPARE TYRE PANEL TOP BOARD	Serviceable	473.50 FL	*- FL
35	1		*REAR EXHAUST SILENCER	Serviceable	1,457.80 FL	*- FL
36	1		*REAR EXHAUST SILENCER GASKET	Serviceable	55.60 FL	*- FL
37	1		*REAR BUMPER RH EXHAUST CHROME FINISHER	Scratched	450.00 FS	*250.00 FS
38	1		*REAR BUMPER LH EXHAUST CHROME FINISHER	Serviceable	450.00 FS	*- FS
39	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*40.00 FS
40	1		*BOOTLID SPOILER	Serviceable	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,812.38	10,343.38
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,364.24	1,005.34

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	14,448.14
						9,338.04
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING ON AFFECTED AREAS AND PANELS	New	80.00	30.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	120.00	40.00
6	REMOVE AND REPLACE REAR INNER TRIM AND GARNISH	New	280.00	70.00
7	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	380.00	0.00
Gross Labour Cost (\$\$)			3,640.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >