

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III22003426/RTY3E2

Date: 31/05/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SLL8474H Insured Vehicle No : SLM1499C

Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: MFL2022D0001658

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL8474H
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2978992
Reg. Date: 20/11/2007 (Man. Year: 2007) Chassis No: ZNE100384130
Colour: Blue Odometer: 334716 km
Engine Capacity: 1794 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,703.09	4,044.40	13,658.69	77.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	3,000.00	1,460.00	32.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,163.09	7,044.40	15,118.69	68.22
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	22,163.09	3,000.00	19,163.09	86.46

INSPECTION

Date of Assignment: 13/04/2022

Date Inspected: 13/04/2022 Inspected At:

Hing Lee Motor Car Repair & Welder Works (HQ)
397D Woodlands Road
Singapore 677996

Estimated Period of Repair: 11.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL8474H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	804.00 F	*625.00 FL
2	1		*FRONT HEAD LAMP ASSY	Not Necessary	1,214.10 F	*- FL
3	1		*FRONT RH BUMPER RETAINER	Necessary	171.75 F	*72.65 FL
4	1		*FRONT RH FENDER LINER	Cut	371.45 F	*155.60 FL
5	1		*SET FRONT RH FENDER CLIP	Necessary	50.00 FS	*30.00 FS
6	1		*FRONT RH ROAD WHEEL (SPORT) RIM	Bent	580.00 FS	*350.00 FS
7	1		*FRONT RH TYRE	Not Necessary	380.00 FS	*- FS
8	1		*FRONT RH SHOCK ABSORBER	Not Necessary	417.90 F	*- FL
9	1		*FRONT RH LOWER ARM	Not Necessary	422.18 F	*- FL
10	1		*FRONT RH KNUCKLE	Not Necessary	571.10 F	*- FL
11	1		*FRONT RH KNUCKLE BEARING	Not Necessary	230.16 F	*- FL
12	1		*FRONT LH ROAD WHEEL (SPORT) RIM	Scratched	580.00 FS	*350.00 FS
13	1		*FRONT LH SHOCK ABSORBER	Not Necessary	417.90 F	*- FL
14	1		*FRONT LH LOWER ARM	Not Necessary	422.18 F	*- FL
15	1		*FRONT LH KNUCKLE	Not Necessary	571.10 F	*- FL
16	1		*FRONT LH KNUCKLE BEARING	Not Necessary	230.16 F	*- FL
17	1		*FRONT LH TYRE	Not Necessary	380.00 FS	*- FS
18	1		*FRONT RH FOG LAMP	Not Necessary	399.10 F	*- FL
19	1		*SET RH DOOR WISER	Necessary	150.00 FS	*120.00 FS
20	1		*REAR RH DOOR ASSY	Torn	1,012.00 F	*1,012.00 FL
21	1		*REAR RH DOOR REGULATOR	Not Necessary	421.20 F	*- FL
22	1		*REAR RH DOOR TRIM BOARD	Not Necessary	971.10 F	*- FL
23	1		*REAR RH DOOR GLASS OUTER W/STRIP	Necessary	271.74 F	*138.40 FL
24	1		*REAR RH DOOR W/STRIP	Necessary	289.40 F	*176.50 FL
25	1		*REAR RH DOOR INNER LOCK	Not Necessary	571.10 F	*- FL
26	1		*REAR RH DOOR OUTER HANDLE	Not Necessary	178.10 F	*- FL
27	1		*REAR RH DOOR HINGES LOWER	Not Necessary	177.30 F	*- FL
28	1		*REAR RH DOOR HINGE TOP	Not Necessary	187.20 F	*- FL
29	1		*REAR RH ROCKER PANEL	Bent	688.45 F	*301.20 FL
30	1		*FRONT RH DOOR ASSY	Bent	1,217.85 F	*1,217.85 FL
31	1		*FRONT RH DOOR INNER LOCK	Not Necessary	571.10 F	*- FL
32	1		*FRONT RH DOOR W/STRIP	Necessary	321.10 F	*215.00 FL
33	1		*FRONT RH DOOR GLASS OUTER W/STRIP	Necessary	371.75 F	*149.40 FL
34	1		*CENTRE DOOR PILLAR RH	Repair	821.22 F	*- FL
35	1		*FRONT BUMPER BEAM	Not Necessary	465.50 F	*- FL
36	1		*FRONT RH BUMPER BEAM BRACKET	Not Necessary	172.25 F	*- FL
37	1		*FRONT BUMPER SPONGE	Not Necessary	210.20 F	*- FL
38	1		*FRONT LH FENDER LINER	Deformed	371.45 F	*155.60 FL
39	1		*SET FRONT LH FENDER LINER CLIP	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,703.09	5,099.20
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,054.80
Total Parts (\$)	17,703.09	4,044.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRONT & REAR RH DOOR GLASS REMOVE & REFIT	New	120.00	80.00
2	WIRING FEE	New	50.00	30.00
3	ANTI RUST	New	120.00	80.00
4	UNDERCARRIAGE FRONT REPAIR & REFIT R&L	New	400.00	300.00
5	WHEEL ALIGNMENT	New	120.00	80.00
6	TO RESPRAY PAINTING DAMAGE PORTION	New	2,000.00	1,250.00
7	TO REPAIR ACC DAMAGE PORTION	New	1,500.00	1,100.00
8	CAR SEAT & INTERIOR REMOVE & REFIT	New	150.00	80.00
Gross Labour Cost (\$)			4,460.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >