

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003429/DNY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00073792101
Claimant Vehicle No :	SBU72H	Insured Vehicle No :	GBK4414G
Date of Loss:	12/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202497/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBU72H	Engine No:	FA20A974430
Make & Model:	SUBARU FORESTER, 2.0 XT CVT AWD SR (A)	Chassis No:	JF1SJGK85GG074890
Reg. Date:	19/08/2016 (Man. Year: 2016)	Odometer:	66484 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,826.48	3,503.44	23,323.04	86.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,200.00	850.00	4,350.00	83.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,026.48	4,353.44	27,673.04	86.41
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	32,026.48	3,400.00	28,626.48	89.38
+ GST 7.00/7.00% (\$\$)	2,241.85	238.00	2,003.85	89.38
Nett Amount (\$\$)	34,268.33	3,638.00	30,630.33	89.38

INSPECTION

Date of Assignment:	13/04/2022	
Date Inspected:	13/04/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBU72H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,440.00 FL	*- FL
2	2		*BONNET HINGE LH/RH	Not Necessary	304.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	656.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	378.30 FL	*- FL
5	1		*BONNET STRIKER LOCK	Not Necessary	99.00 FL	*- FL
6	1		*BONNET CHROME MOULDING	Not Necessary	619.20 FL	*- FL
7	1		*FRONT GRILLE	Cut / Mtg Cracked	710.00 FL	*316.80 FL
8	1		*FRONT GRILLE LOGO	Not Necessary	95.00 FL	*- FL
9	1		*FRONT GRILLE CHROME MOULDING TOP	Not Necessary	374.00 FL	*- FL
10	1		*FRONT GRILLE CHROME MOULDING LOWER	Cut / Distorted	431.00 FL	*180.00 FL
11	1		*HEAD LAMP LH	Mtg Cracked	4,360.00 FL	*2,380.00 FL
12	1		*HEAD LAMP LOWER BRACKET LH	Cracked	195.00 FL	*110.00 FL
13	1		*HEAD LAMP ECU LH	Not Necessary	1,780.00 FL	*- FL
14	1		*HEAD LAMP WIRE HARNESS COMPLETE	Not Necessary	1,960.00 FL	*- FL
15	1		*HEAD LAMP NOZZLE COVER LH	Dislodged	241.00 FL	*54.00 FL
16	1		*FRONT BUMPER	Distorted	1,650.00 FL	*660.30 FL
17	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	298.00 FL	*- FL
18	1		*FRONT BUMPER LOWER LID	Not Necessary	620.00 FL	*- FL
19	1		*FRONT BUMPER UNDER COVER	Not Necessary	298.50 FL	*- FL
20	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	885.00 FL	*- FL
21	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	370.00 FL	*- FL
22	1		*FRONT BUMPER FOG LAMP CHROME MOULDING RH	Not Necessary	451.00 FL	*- FL
23	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,988.00 FL	*- FL
24	1		*FRONT BUMPER BRACKET	Not Necessary	760.00 FL	*- FL
25	1		*FRONT REINFORCEMENT BAR	Dented	1,480.00 FL	*499.00 FL
26	2		*FRONT REINFORCEMENT HOLDER LH/RH	Not Necessary	580.00 FL	*- FL
27	1		*FRONT SUPPORT PANEL	Not Necessary	1,682.00 FL	*- FL
28	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	365.00 FL	*- FL
29	1		*A/C CONDENSOR ASSY	Not Necessary	1,820.80 FL	*- FL
30	1		*A/C CONDENSOR HIGH PRESSURE HOSE	Not Necessary	810.00 FL	*- FL
31	1		*A/C CONDENSOR LOW PRESSURE HOSE	Not Necessary	415.00 FL	*- FL
32	1		*RADIATOR ASSY	Not Necessary	2,229.00 FL	*- FL
33	1		*RADIATOR FAN MOTOR	Not Necessary	385.60 FL	*- FL
34	1		*RADIATOR FAN BLADE	Not Necessary	379.20 FL	*- FL
35	1		*RADIATOR FAN COWLING	Not Necessary	418.50 FL	*- FL
36	1		*HEADLAMP NOZZLE LH	Mtg Cracked	380.00 FL	*79.20 FL
37	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
40	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
41	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*COOLANT	Not Necessary	100.00 FS	*- FS
44	1		*FRONT NO PLATE & CASING	Bent	100.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)33,408.104,359.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					6,581.62	855.86
Total Parts (S\$)					26,826.48	3,503.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	300.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
5	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	120.00
Gross Labour Cost (\$\$)			5,200.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >