

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFX 8088Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED / CRACKED	1,033.10	1,033.10
1	REAR BUMPER BEAM (CONSISTENT)	TO REPAIR SEE LABOUR	488.50	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	645.10	-
	LESS 25% DISCOUNT		-541.68	-258.28
			1,625.02	774.82
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
			330.00	250.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIX REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIX CUSHION UPHOLSTERY .		100.00	60.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM AND REAR END PANEL .		700.00	400.00
	SPRAY PAINTING.		800.00	400.00
			1,850.00	930.00
	GRAND TOTAL		3,805.02	1,954.82

RECOMMENDED COST OF LUMP SUM REPAIRS		1,500.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM22003431/Uga3q2

CHUA KANG SENG

Licensed Appraiser