

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003440/APA3Q2**Date:** 12/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100379284-07
Claimant Vehicle No :	SMN1174Y	Insured Vehicle No :	GBD1469E
Date of Loss:	11/04/2022	Nature of Claim:	TP
		Claim No:	1396946521SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN1174Y		
Make & Model:	MERCEDES-BENZ B180, 1.6 AMG LINE (R18 LED) (A)	Engine No:	27091030673498
Reg. Date:	08/03/2016 (Man. Year: 2015)	Chassis No:	WDD2462422J329041
Colour:	Red	Odometer:	98323 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,084.79	1,588.08	496.71	23.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	580.00	370.00	38.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,034.79	2,168.08	866.71	28.56
+ GST 7.00/7.00% (S\$)	212.44	151.77	60.67	28.56
Nett Amount (S\$)	3,247.23	2,319.85	927.38	28.56
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,501.85		

INSPECTION

Date of Assignment:	21/04/2022	
Date Inspected:	21/04/2022	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,458.60 FL	*1,458.60 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Not Necessary	170.00 FL	*- FL
3	1		*REAR BUMPER LOWER GARNISH	Not Necessary	381.90 FL	*- FL
4	1		*REAR BUMPER TOP CHROME MOULDING	Necessary	272.60 FL	*272.60 FL
5	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	2,313.10 1,761.20
					- List Item Discount on L Items 10.00/10.00% (\$\$)	228.31 173.12
					Total Parts (\$\$)	2,084.79 1,588.08

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	400.00	250.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	400.00	250.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			950.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >