

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22003441/ENY3Q2**Date:** 05/06/2023**REFERENCE**

Insured/Claimant:	SINGAPORE COACH SERVICES PTE LTD	Policy No:	DMB1SNA00008542101
Date of Loss:	11/04/2022	Nature of Claim:	OD
		Claim No:	SNM22D202498/C01/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	PC5592U	Engine No:	ISB67E528522076980
Make & Model:	KING LONG XMQ6117K, 6.7 (A)	Chassis No:	LA6R1FSH8GB402380
Reg. Date:	12/01/2017 (Man. Year: 2016)	Odometer:	230090 km
Colour:	Multi-colour		
Engine Capacity:	6691 cc		
Market Value/New Car Price:	S\$121,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

**CONDITION OF TYRES**

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	77,885.00	74,195.00	3,690.00	4.74
Miscellaneous Items	880.00	880.00	0.00	0.00
Labour	7,450.00	6,700.00	750.00	10.07
Paintwork Labour	1,200.00	1,000.00	200.00	16.67
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>87,415.00</b>	<b>82,775.00</b>	<b>4,640.00</b>	<b>5.31</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>66,200.00</b>		
<b>- Excess (S\$)</b>	2,500.00	2,500.00	0.00	0.00
<b>(S\$)</b>	84,915.00	63,700.00	21,215.00	24.98
<b>+ GST 7.00/8.00% (S\$)</b>	5,944.05	5,096.00	848.05	14.27
<b>Nett Amount (S\$)</b>	<b>90,859.05</b>	<b>68,796.00</b>	<b>22,063.05</b>	<b>24.28</b>

**INSPECTION**

Date of Assignment:	13/04/2022	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	14/04/2022	Inspected At:	566 Woodlands Rd, Singapore 728697
Estimated Period of Repair:	50.0 days	Repairer:	Auto Insure Pte Ltd (HQ) (Woodlands)

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Jun 2023)	
<b>Parts:</b>	N/A	KING LONG XMQ6117K 6.7 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC5592U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR LH	Not Necessary	1,215.00 F	*- F
2	1		*SIDE MIRROR RH	Not Necessary	1,215.00 F	*- F
3	1		*FRONT WIPER ARM LH	Cut	139.50 F	*139.50 F
4	1		*FRONT WIPER ARM RH	Cut	139.50 F	*139.50 F
5	1		*FRONT RH LINKAGE	Dented	1,080.00 F	*1,080.00 F
6	1		*FRONT WINDSCREEN	Broken	3,420.00 F	*3,420.00 F
7	1		*FRONT DRIVER SIDE GLASS	Dented	720.00 F	*720.00 F
8	1		*FRONT ROOF PANEL	Dented	9,450.00 F	*9,450.00 F
9	1		*FRONT ROOF PANEL INNER TRIM	Crushed	8,370.00 F	*8,370.00 F
10	1		*FRONT ROOF PANEL STRUCTURE	Bent	7,740.00 F	*7,740.00 F
11	1		*CENTER ROOF PANEL	Dented	3,780.00 F	*3,780.00 F
12	1		*CENTER ROOF PANEL STRUCTURE	Bent	2,790.00 F	*2,790.00 F
13	1		*A PILLAR RH	Dented	2,520.00 F	*2,520.00 F
14	1		*A PILLAR INNER TRIM RH	Not Necessary	1,260.00 F	*- F
15	1		*ROOF AC ASSEMBLY	Broken	25,200.00 F	*25,200.00 F
16	1		*ROOF AC ASSEMBLY COVER	Broken	3,330.00 F	*3,330.00 F
17	1		*CABIN AC DUCT RH	Broken	1,215.00 F	*1,215.00 F
18	1		*CABIN AC DUCT TRIM RH	Crushed	648.00 F	*648.00 F
19	1		*CABIN AC DUCT TRIM GUIDE RH	Crushed	729.00 F	*729.00 F
20	1		*ERP BRACKET	Necessary	26.00 F	*26.00 F
21	1		*FRONT WINDSCREEN MOULDING	Necessary	288.00 F	*288.00 F
22	1		*CENTER ROOF PANEL INNER TRIM	Crushed	2,610.00 F	*2,610.00 F

F=Franchise part.

**Total Parts (S\$)**      **77,885.00**      **74,195.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	AIRCON GAS (NECESSARY)	200.00	200.00
2	1	FRONT DRIVER SIDE GLASS SEALANT (NECESSARY)	40.00	40.00
3	1	FRONT WINDSCREEN SEALANT (NECESSARY)	320.00	320.00
4	1	SIDE GLASS SEALANT (NECESSARY)	320.00	320.00
Sub Total (S\$)			880.00	880.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	LABOUR FOR SPRAY PAINTING	New	1,200.00	1,000.00
<b>Labour Items</b>				
2	LABOUR FOR PANEL BEATING	New	3,000.00	2,700.00
3	LABOUR TO REMOVE AND REFIT FRONT WINDSCREEN	New	800.00	800.00
4	LABOUR TO REMOVE AND REFIT DRIVER GLASS	New	200.00	200.00
5	LABOUR TO REMOVE AND REFIT SIDE GLASS	New	1,500.00	1,300.00
6	LABOUR TO REMOVE AND REFIT INNER TRIMS	New	900.00	700.00
7	LABOUR TO REMOVE AND REFIT ROOFTOP AIRCON	New	600.00	600.00
8	LABOUR TO CHECK WIRING	New	250.00	200.00
9	LABOUR FOR RUSTPROOFING	New	200.00	200.00
Gross Labour Cost (S\$)			8,650.00	7,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >