

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22003443/VCY3E2

Date: 02/08/2022

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000206	
Claimant Vehicle No :	SHB6234Y	Insured Vehicle No :	SLM7149Z	
Date of Loss:	13/04/2022	Nature of Claim:	TP	Claim No: M2201769

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6234Y	Engine No:	D4FDGU656068
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU097910
Reg. Date:	05/01/2017 (Man. Year: 2016)	Odometer:	546276 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,692.16	2,692.16	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,400.00	1,260.00	140.00	10.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,103.16	3,963.16	140.00	3.41
Approved Total (Overridden) (S\$)		3,150.00		
(S\$)	4,103.16	3,150.00	953.16	23.23
+ GST 7.00/7.00% (S\$)	287.22	220.50	66.72	23.23
Nett Amount (S\$)	4,390.38	3,370.50	1,019.88	23.23

INSPECTION

Date of Assignment:	14/04/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/04/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2022)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6234Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Dented	1,052.20 FL	*1,052.20 FL
2	1		*FRT FENDER LH	Dented	663.00 FL	*663.00 FL
3	1		*HEADLAMP ASSY LH	Scratched	1,388.00 FL	*1,388.00 FL
4	1		*FRT WHEEL CAP	Scratched	217.20 FL	*217.20 FL
5	1		*FRT BUMPER BRACKET LH	Necessary	44.80 FL	*44.80 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					3,365.20	3,365.20
- List Item Discount on L Items 20.00/20.00% (S\$)					673.04	673.04
Total Parts (S\$)					2,692.16	2,692.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	700.00
2	SPRAYPAINT	New	600.00	500.00
3	TUFF KOTE	New	50.00	30.00
4	CHECK WIRING	New	50.00	30.00
Gross Labour Cost (\$\$)			1,400.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >