

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22003444/UEA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SNB1580J **Insured Vehicle No :** SNA4036A

Date of Loss: 10/04/2022 Nature of Claim: TP Claim No: MFL2022D0001942

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB1580J**

Make & Model: BMW 320I, 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A) Engine No: A356J804N13B16A

Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: WBA3J92020J642366

Colour: Blue Odometer: 111330 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55Z R16 Rear Tyre Size: 215/55Z R16

Front Left Side: Reac 6 mm Rear Left Side: Volex 6 mm

Front Right Side: Reac 6 mm Rear Right Side: Volex 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts (after Betterment)	5,026.38	3,349.27	1,677.11	33.37
Miscellaneous Items	18.00	11.00	7.00	38.89
Labour	4,150.00	1,930.00	2,220.00	53.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,194.38	5,290.27	3,904.11	42.46
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	9,194.38	4,200.00	4,994.38	54.32
+ GST 7.00/7.00% (S\$)	643.61	294.00	349.61	54.32
Nett Amount (S\$)	9,837.99	4,494.00	5,343.99	54.32
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,929.45		

INSPECTION

Date of Assignment: 14/04/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)

Date Inspected: 18/04/2022 Inspected At: Car City Auto Centre Pte Ltd (HQ)
Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2022)

Parts: 143 BMW 320I 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB1580J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,247.30 FL (5.00/5)%	*- FL
2	1		*BMW LOGO	Not Necessary	82.15 FL (5.00/5)%	*- FL
3	1		*320I EMBLEM	Necessary	75.15 FL (5.00/5)%	*75.15 FL
4	1		*REAR BUMPER	Distorted	1,167.05 FL (5.00/5)%	*1,167.05 FL
5	1		*REAR BUMPER BOTTOM REINFORCEMENT	Cracked	95.15 FL (5.00/5)%	*95.15 FL
6	1		*REAR BUMPER GUIDE LH	Cracked	153.50 FL (5.00/5)%	*153.50 FL
7	1		*REAR BUMPER GUIDE CENTER	Cracked	153.50 FL (5.00/5)%	*153.50 FL
8	1		*REAR BUMPER PROTECTION FOIL LH	No such part	30.75 FL (5.00/5)%	*- FL
9	1		*REAR BUMPER REFLECTOR LH	Cracked	45.30 FL (5.00/5)%	*45.30 FL
10	1		*REAR BUMPER CARRIER	Bent	470.25 FL (5.00/5)%	*470.25 FL
11	1		*LH REAR UNDER PANELLING	Torn	71.20 FL (5.00/5)%	*71.20 FL
12	1		*TAILLAMP LH	Not Necessary	392.00 FL (5.00/5)%	*- FL
13	1		*REAR ULTRA SENSOR LH	Shorted	239.25 FL (5.00/5)%	*239.25 FL
14	1		*REAR ULTRA SENSOR RING LH	Necessary	9.05 FL (5.00/5)%	*9.05 FL
15	1		*REAR ULTRA SENSOR WIRE HARNESS	Not Necessary	284.35 FL (5.00/5)%	*- FL
16	1		*REAR EXHAUST MUFFLER	Repair	1,025.30 FL (5.00/5)%	*- FL
17	1		*REAR EXHAUST MUFFLER MOUNTING	Torn	28.15 FL (5.00/5)%	*28.15 FL
18	1		*REAR END PANEL	Dented	-	*1,018.00 FL

F=Franchise part. L=ListItemDisc. (x/y)%=(PDisc/Depr)%.

Sub Total (\$\$)	5,569.40	3,525.55
- List Item Discount on L Items 5.00/5.00% (\$\$)	278.47	176.28
Total Parts (\$\$)	5,290.93	3,349.27
- Betterment 0.00/0.00% (\$\$)	264.55	0.00
Total Parts after Betterment (\$\$)	5,026.38	3,349.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	LTA SEARCH FEE	7.00	0.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			18.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,ALIGN,REPLACE BOOT LID,REAR BUMPER,REAR END PANEL,LHR FENDER,REINFORCEMENT AND AFFECTED AREA	New	1,200.00	800.00
2	TO PUTTY AND RESPRAY PAINT ON BOOT LID,REAR BUMPER,REAR END PANEL,LHR FENDER,REINFORCEMENT AND AFFECTED AREA	New	1,500.00	800.00
3	TO APPLY TUFF KOTE	New	250.00	30.00
4	TO REMOVE AND REFIT UPHOISTERY AND SEATS TO ASSIST WORK	New	400.00	80.00
5	TO REMOVE AND INSTALL ULTRA SENSOR AND WIRING	Repair	200.00	50.00
6	TO REMOVE AND INSTALL EXHAUST SYSTEM	New	250.00	100.00
7	TO RESET FAULT CODE	New	250.00	50.00
8	TO CHECK WIRING	New	100.00	20.00
Gross Labour Cost (\$\$)			4,150.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >