

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SNB1580J

at Workshop m/s

Car city

of

Insured:

SNA 4036A

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$55k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

975-i
Vehicle: IN / OUT

Date:

Person Contacted:

27A 36816

Date / Time

Action / Instruction

Rep 16k.

28/4/22 informed Anson 2/5 \$4200

Veh No:

SNB1580J

Yr Regn:

30/10/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

BMW 320i

c.c

1598

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp.Reading

111330

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA3J92020J642366

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/55-ZR16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/04/22

D.O.I.

18/4/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

**CAR CITY AUTO CENTRE PTE LTD**

Blk 9006 Tampines Street 93 #01-198 Singapore 528840

TEL: (65) 85114276 FAX: (65) 67820300 EMAIL: ccapl@singtel.com.sg

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SNB 1580 JMake & Model : BMW 320Year of Manufacture : 2014Chassis No. : WBA3J92020J642366

Engine No. : _____

Policy No. : _____

Time of Accident : 11.40AMIns Company : CHINA

Excess : _____

Date of Accident : 10/04/2022Suggested Days of Repair : 7**Service Advisor** : _____**Repair Estimates****Parts** (a) Cost / List Price Items \$ 5,569.40Plus/Less 5% \$ 278.47Total of Cost / List \$ 5,290.93(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items _____

Total Parts Cost (Appendix A) \$ 5,290.93**Labour (Appendix B)** \$ 4,150.00**Total Repair Cost** \$ 9,440.93

LKK Auto Consultants hence notify the Repairer of the following:

In-house Vehicle Assessor _____

Case Owner _____

Signature _____

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : nerous

Company : LM

Survey conducted on : 18/4/22 at 12 m.

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$ not Allowed

(e) Signature of surveyor : nerous Date: _____

ACCIDENT REPAIR ESTIMATES\F3

92096608

P- 325.55'

5%


P- 3349.27

L- 1930

5279.27

203

4223.



CAR CITY AUTO CENTRE PTE LTD

Blk 9006 Tampines Street 93 #01-198 Singapore 528840

TEL: (65) 85114276 FAX: (65) 67820300 EMAIL: ccapl@singtel.com.sg

ESTIMATED REPAIR COST DETAILS

Vehicle No : SNB 1580 J

Case Owner : 0

Make & Model : BMW 320

Year Manufacture : 2014

Chassis No : WBA3J92020J642366

Engine No : 0

Date & Time : _____


Supplier : _____

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	BOOT LID	1		\$ 1,247.30	R	X
2	BMW LOGO	1		\$ 82.15	111	X
3	320I EMBLEM	1		\$ 75.15	111	✓
4	REAR BUMPER	1		\$ 1,167.05	111	✓
5	REAR BUMPER BOTTOM REINFORCEMENT	1		\$ 95.15	111	✓
6	REAR BUMPER LH GUIDE	1		\$ 153.50	111	✓
7	REAR BUMPER CENTER GUIDE	1		\$ 153.50	111	✓
8	REAR BUMPER PROTECTION FOIL	1		\$ 30.75	111	X
9	REAR BUMPER REFLECTOR LH	1		\$ 45.30	111	✓
10	REAR BUMPER CARRIER	1		\$ 470.25	111	✓
11	LH REAR UNDER PANELLING	1		\$ 71.20	111	✓
12	TAILLAMP LH	1		\$ 392.00	111	✓
13	REAR ULTRA SENSOR LH	1		\$ 239.25	111	✓
14	REAR ULTRA SENSOR RING LH	1		\$ 9.05	111	✓
15	REAR ULTRA SENSOR WIRE HARNESS	1		\$ 284.35	111	X
16	REAR EXHAUST MUFFLER	1		\$ 1,025.30	111	✓
17	REAR EXHAUST MUFFLER MOUNTING	1		\$ 28.15	111	✓
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



CAR CITY AUTO CENTRE PTE LTD

Blk 9006 Tampines Street 93 #01-198 Singapore 528840

TEL: (65) 85114276 FAX: (65) 67820300 EMAIL: ccapl@singtel.com.sg

Supplementary 1




Vehicle No : SNB 1580 J Case Owner : 0

Make & Model : BMW 320 Year Manufacture : 2014

Chassis No : WBA3J92020J642366 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	REAR END PANEL 			\$1,018.00			
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Case Owner : _____
Year of Manufacture : _____

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.