

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22003445/APA3Q2**Date:** 12/09/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7990000064   |
| <b>Claimant Vehicle No :</b> | SJN1784Y                             | <b>Insured Vehicle No :</b> | GBK3359P     |
| Date of Loss:                | 11/04/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 5149899427SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJN1784Y</b>                   | Engine No:  | 1NZX856870        |
| Make & Model:               | TOYOTA VIOS, 1.5 E (A)            | Chassis No: | MR053HY9305097239 |
| Reg. Date:                  | 06/02/2009 (Man. Year: 2008)      | Odometer:   | 466622 km         |
| Colour:                     | Red                               |             |                   |
| Engine Capacity:            | 1497 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 185/70 R14     | Rear Tyre Size:  | 185/70 R14     |
| Front Left Side:  | GREEN-MAX 6 mm | Rear Left Side:  | GREEN-MAX 6 mm |
| Front Right Side: | GREEN-MAX 6 mm | Rear Right Side: | GREEN-MAX 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 13,459.35         | 4,717.74          | 8,741.61          | 64.95         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 2,720.00          | 2,240.00          | 480.00            | 17.65         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>16,179.35</b>  | <b>6,957.74</b>   | <b>9,221.61</b>   | <b>57.00</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>5,300.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 16,179.35         | 5,300.00          | 10,879.35         | 67.24         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,132.55          | 371.00            | 761.55            | 67.24         |
| <b>Nett Amount (S\$)</b>                        | <b>17,311.90</b>  | <b>5,671.00</b>   | <b>11,640.90</b>  | <b>67.24</b>  |
| <b>+ Loss of Use (8.0 x S\$60.00/day) (S\$)</b> |                   | 480.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>6,158.45</b>   |                   |               |

INSPECTION

|                             |                          |                                                    |
|-----------------------------|--------------------------|----------------------------------------------------|
| Date of Assignment:         | 13/04/2022               | Green Forest Automobile Pte Ltd (Kaki Bukit)       |
| Date Inspected:             | 13/04/2022 Inspected At: | 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit |
| Estimated Period of Repair: | 6.0 days                 | Singapore 415875                                   |

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's | Amount       |
|-----|-----|----------|--------------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *FRONT R/H DOOR                      | Distorted     | 1,069.40 F | *1,069.40 FL |
| 2   | 1   |          | *FRONT R/H DOOR TOP HINGES           | Not Necessary | 155.20 F   | *- FL        |
| 3   | 1   |          | *FRONT R/H DOOR LOWER HINGES         | Not Necessary | 155.20 F   | *- FL        |
| 4   | 1   |          | *FRONT R/H DOOR INNER TRIM BOARD     | Not Necessary | 678.20 F   | *- FL        |
| 5   | 1   |          | *FRONT R/H DOOR INNER LOCK           | Damaged       | 285.20 F   | *285.20 FL   |
| 6   | 1   |          | *FRONT R/H DOOR OUTER HANDLE         | Damaged       | 185.20 F   | *185.20 FL   |
| 7   | 1   |          | *FRONT R/H DOOR INNER RUBBER         | Not Necessary | 261.40 F   | *- FL        |
| 8   | 1   |          | *FRONT R/H DOOR GLASS GEAR           | Damaged       | 321.20 F   | *321.20 FL   |
| 9   | 1   |          | *FRONT R/H DOOR GLASS GEAR MOTOR     | Not Necessary | 412.20 F   | *- FL        |
| 10  | 1   |          | *FRONT R/H DOOR CENTRE PROTECTOR     | Deformed      | 188.20 F   | *188.20 FL   |
| 11  | 1   |          | *FRONT R/H DOOR TOP MOULDING /RUBBER | Deformed      | 185.20 F   | *185.20 FL   |
| 12  | 1   |          | *REAR DOOR CENTER PROTECTOR RH       | Deformed      | 158.20 F   | *158.20 FL   |
| 13  | 1   |          | *R/H DOOR PILLAR                     | Repair        | 981.40 F   | *- FL        |
| 14  | 1   |          | *REAR R/H DOOR                       | Distorted     | 1,069.40 F | *1,069.40 FL |
| 15  | 1   |          | *REAR R/H DOOR TOP HINGES            | Not Necessary | 155.20 F   | *- FL        |
| 16  | 1   |          | *REAR R/H DOOR LOWER HINGES          | Not Necessary | 155.20 F   | *- FL        |
| 17  | 1   |          | *REAR R/H DOOR INNER TRIM BOARD      | Cracked       | 675.20 F   | *510.00 FL   |
| 18  | 1   |          | *REAR R/H DOOR INNER LOCK            | Damaged       | 380.80 F   | *380.80 FL   |
| 19  | 1   |          | *REAR R/H DOOR OUTER HANDLE          | Damaged       | 232.55 F   | *232.55 FL   |
| 20  | 1   |          | *REAR R/H DOOR INNER RUBBER          | Not Necessary | 261.40 F   | *- FL        |
| 21  | 1   |          | *REAR R/H DOOR GLASS GEAR            | Damaged       | 321.20 F   | *321.20 FL   |
| 22  | 1   |          | *REAR R/H DOOR GLASS GEAR MOTOR      | Not Necessary | 422.20 F   | *- FL        |
| 23  | 1   |          | *REAR R/H DOOR TOP MOULDING /RUBBER  | Deformed      | 185.20 F   | *185.20 FL   |
| 24  | 1   |          | *REAR TAIL LAMP -RH                  | Cut           | 333.70 F   | *333.70 FL   |
| 25  | 4   |          | *REAR TAIL LAMP CLIPS                | Necessary     | 26.00 F    | *10.00 FL    |
| 26  | 1   |          | *REAR BUMPER                         | Repair        | 625.20 F   | *- FL        |
| 27  | 8   |          | *REAR BUMPER CLIPS                   | Necessary     | 52.00 F    | *- FL        |
| 28  | 1   |          | *REAR BUMPER REVERSE SENSOR          | Not Necessary | 350.00 F   | *- FL        |
| 29  | 1   |          | *REAR BUMPER BRACKET                 | Not Necessary | 131.70 F   | *- FL        |
| 30  | 1   |          | *REAR BUMPER SIDE REFLECTOR -RH      | Not Necessary | 83.10 F    | *- FL        |
| 31  | 1   |          | *REAR FENDER -RH                     | Repair        | 972.40 F   | *- FL        |
| 32  | 1   |          | *REAR FENDER INNER TRIM BOARD -RH    | Not Necessary | 325.10 F   | *- FL        |
| 33  | 10  |          | *REAR FENDER INNER TRIM BOARD CLIPS  | Not Necessary | 65.00 F    | *- FL        |
| 34  | 1   |          | *REAR TIRE-RH                        | Cut           | 350.00 FS  | *200.00 FS   |
| 35  | 1   |          | *REAR LOWER ARM RH                   | Not Necessary | 282.20 F   | *- FL        |
| 36  | 1   |          | *REAR RIM -RH                        | Cut           | 400.00 F   | *400.00 FL   |
| 37  | 1   |          | *REAR SHOCK ABSORBER -RH             | Not Necessary | 380.20 F   | *- FL        |
| 38  | 1   |          | *REAR BEARING -RH                    | Damaged       | 188.20 F   | *188.20 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                 |
|---------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>13,459.35</b> | <b>6,223.65</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$)</b> | 0.00             | 1,505.91        |
| <b>Total Parts (\$)</b>                                 | <b>13,459.35</b> | <b>4,717.74</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                            | Particulars                          | Lab.Type | Repairer's      | Amount          |
|-------------------------------|--------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                      |          |                 |                 |
| 1                             | TO REMOVE & REFIT CUSHION            | New      | 120.00          | 120.00          |
| 2                             | TO REMOVE & REFIT REVERSE SENSOR     | New      | 100.00          | 50.00           |
| 3                             | TO REMOVE & REFIX REAR UNDERCARRIAGE | New      | 200.00          | 180.00          |
| 4                             | TO CHECK WIRING                      | New      | 60.00           | 30.00           |
| 5                             | WHEEL ALIGNMENT (COMPUTER)           | New      | 120.00          | 80.00           |
| 6                             | TUFF KOTE                            | New      | 120.00          | 80.00           |
| 7                             | PANEL BEATING                        | New      | 1,000.00        | 800.00          |
| 8                             | SPRAY PAINTING                       | New      | 1,000.00        | 900.00          |
| <b>Gross Labour Cost (\$)</b> |                                      |          | <b>2,720.00</b> | <b>2,240.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >