

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003446/KPA3Q2**Date:** 23/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700074608
Claimant Vehicle No :	SJX3435P	Insured Vehicle No :	SLT9094Y
Date of Loss:	13/04/2022	Nature of Claim:	TP
		Claim No:	5353654368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX3435P	Engine No:	1NZY101559
Make & Model:	TOYOTA VIOS, 1.5 G (A)	Chassis No:	MR053HY9305168705
Reg. Date:	03/06/2010 (Man. Year: 2010)	Odometer:	56780 km
Colour:	Metallic Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,343.80	2,606.42	2,737.38	51.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,660.00	1,120.00	40.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,123.80	4,266.42	3,857.38	47.48
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	8,123.80	3,400.00	4,723.80	58.15
+ Car Rental (6.5 x S\$100.00/day) (S\$)		650.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,057.45		

INSPECTION

Date of Assignment:	18/04/2022	Lim Yew Boo Spray Paint Co (HQ)
Date Inspected:	18/04/2022 Inspected At:	NO. 176 SIN MING DRIVE #03-05, SIN MING IND EST
Estimated Period of Repair:	6.0 days	Singapore 575645

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	495.50 FL	*488.10 FL
2	2		*REAR BUMPER BRACKETS	Repair	140.40 FL	*- FL
3	1		*REAR BUMPER RETAINER	O/S Distorted	60.40 FL	*30.20 FL
4	1		*REAR LID	Bent	641.60 FL	*618.20 FL
5	1		*REAR LID RUBBER (50%)	Distorted / Dented	121.35 FS	*80.90 FS
6	2		*REAR LID HINGES	Repair	98.40 FL	*- FL
7	1		*REAR LID LOCK (UPPER)	Dented	90.70 FL	*90.70 FL
8	1		*REAR LID LOCK (LOWER)	Repair	45.70 FL	*- FL
9	1		*REAR LID OUTER CHROME	Serviceable	189.90 FL	*- FL
10	1		*REAR TAILEND PANEL	Bent	738.00 FL	*588.30 FL
11	1		*REAR TAILEND TOP GARNISH	Dented	219.90 FL	*158.60 FL
12	2		*REAR TAILLAMP ASSY	Cracked	759.40 FL	*759.40 FL
13	2		*REAR EMBLEM LOGO TOYOTA	Necessary (1 PCSO ONLY)	194.40 FL	*59.50 FL
14	1		*REAR EMBLEM VIOS	Necessary	67.90 FL	*59.30 FL
15	12		*REAR EMBLEM G	Necessary (1 PCS ONLY)	694.80 FL	*45.00 FL
16	1		*REAR SILENCER	Repair	879.00 FL	*- FL
17	1		*REAR SPARE TYRE PANEL	Repair	931.60 FL	*- FL
18	2		*REAR TAILLAMP GASKET	Necessary	73.40 FL	*73.40 FL
19	1		*REAR TAILEND PANEL TEROSTAT SEALANT	Necessary	54.20 FS	*30.00 FS
20	5		*REAR TAILEND TOP GARNISH CLIPS	Necessary	27.50 FS	*27.50 FS
21	5		*REAR BUMPER FASTENER	Necessary	40.00 FS	*40.00 FS
22	5		*REAR BUMPER EXTENSION FASTENER	Not Necessary	40.00 FS	*- FS
23	5		*REAR BUMPER EXTENSION GROMMET SCREW	Not Necessary	40.00 FS	*- FS
24	1		*SET REAR REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
25	1		*REAR NO PLATE	Serviceable	35.00 FS	*- FS
26	1		*REAR NO PLATE HOLDER	Serviceable	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,924.05	3,349.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,580.25	742.68
Total Parts (\$\$)	5,343.80	2,606.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK & REPAIR/ REPLACE EXHAUST SILENCER	New	180.00	60.00
2	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	New	80.00	50.00
3	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	60.00
4	TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID	New	80.00	50.00
5	TO CHECK WATER SEEPAGE	New	60.00	20.00
6	TO CHECK WIRING FUNCTION	New	60.00	20.00
7	TO REPAIR ,PANEL BEAT ,ALIGN ,CUT & WELD ON REAR END PANEL ,REAR SPARE TYRE PANEL & LABOUR TO REPLACE THE ABOVE PARTS	New	1,000.00	600.00
8	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR BOOT LID ,REAR REAR SPARE TYRE PANEL ,REAR TAILEND PANEL ,REAR BUMPER ,REAR REVERSE SENSOR USING 2K PAINT	New	1,200.00	800.00
Gross Labour Cost (\$\$)			2,780.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >