

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22003449/KTY3E2

Date: 07/06/2022

REFERENCE

Insured/Claimant:	BIS MOTORING PTE. LTD.	Policy No:	MCF22A00000100	
Date of Loss:	06/04/2022	Nature of Claim:	OD	Claim No: DMCF2200003H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA8822H	Engine No:	D4FDJD028343
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7212222
Reg. Date:	07/11/2018 (Man. Year: 2018)	Odometer:	332783 km
Colour:	Metallic Black		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Grenlander 8 mm	Rear Left Side:	DURATURN 8 mm
Front Right Side:	Grenlander 8 mm	Rear Right Side:	DURATURN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,355.75	8,599.25	3,756.50	30.40
Miscellaneous Items	144.00	67.00	77.00	53.47
Labour	4,690.00	2,580.00	2,110.00	44.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,189.75	11,246.25	5,943.50	34.58
Approved Total (Overridden) (S\$)		10,700.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	15,189.75	8,700.00	6,489.75	42.72
+ GST 7.00/7.00% (S\$)	1,063.28	609.00	454.28	42.72
Nett Amount (S\$)	16,253.03	9,309.00	6,944.03	42.72

INSPECTION

Date of Assignment:	14/04/2022	Present Location:	Munich Autocare Pte Ltd (HQ)
Date Inspected:	14/04/2022	Inspected At:	Munich Autocare Pte Ltd (HQ) 60 Jalan Lam Huat, #07-43 Singapore 737869
Estimated Period of Repair:	8.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	M1-MPV	KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA8822H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*front bonnet (WCP)	Bent	420.00 F	*420.00 F
2	1		*front bonnet lock (WCP)	Distorted	49.00 F	*49.00 F
3	1		*front bonnet insulation (WCP)	Serviceable	70.00 F	*- F
4	1		*front bonnet hinge LH (WCP)	Bent	25.00 F	*25.00 F
5	1		*front bonnet hinge RH (WCP)	Bent	25.00 F	*25.00 F
6	1		*Front bumper (WCP)	Cracked	350.00 F	*350.00 F
7	1		*front radiator grille (WCP)	Cracked	252.00 F	*252.00 F
8	1		*front bumper top cover (WCP)	Cracked	55.00 F	*55.00 F
9	1		*front headlamp LH (WCP)	Mtg Cracked	880.00 F	*880.00 F
10	1		*front headlamp RH (WCP)	Mtg Cracked	880.00 F	*880.00 F
11	1		*front headlamp bracket LH (WCP)	Serviceable	12.00 F	*- F
12	1		*front headlamp bracket RH (WCP)	Serviceable	12.00 F	*- F
13	1		*front bumper sponge (WCP)	Cracked	56.00 F	*56.00 F
14	1		*front bumper Reinforcement (WCP)	Bent	224.00 F	*224.00 F
15	1		*front support panel (WCP)	Bent	350.00 F	*350.00 F
16	1		*front fender LH (WCP)	Bent	220.00 F	*220.00 F
17	1		*front fender RH (WCP)	Bent	220.00 F	*220.00 F
18	1		*front inter cooler (WCP)	Serviceable	490.00 F	*- F
19	1		*front a/cond condensor (WCP)	Serviceable	420.00 F	*- F
20	1		*front radiator assy (WCP)	Serviceable	420.00 F	*- F
21	1		*front fan cooling fan cowing (WCP)	Serviceable	420.00 F	*- F
22	1		*front intake cover (WCP)	Cracked	84.00 F	*84.00 F
23	1		*front outlet manifold (WCP)	Serviceable	500.00 F	*- F
24	1		*front dash board assy (WCP)	Torn	1,190.00 F	*400.00 F
25	1		*front steering air bag (WCP)	Burst	980.00 F	*980.00 F
26	1		*front passenger air bag (WCP)	Burst	700.00 F	*700.00 F
27	1		*front seat belt LH (WCP)	Jammed	280.00 F	*280.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*front seat belt RH (WCP)	Jammed	280.00 F	*280.00 F
29	1		*front seat belt tensioner LH (WCP)	Serviceable	280.00 F	*- F
30	1		*front seat belt tensioner RH (WCP)	Jammed	280.00 F	*280.00 F
31	1		*clock spring (WCP)	Necessary	126.00 F	*125.00 F
32	1		*air bag computer unit (WCP)	Necessary	560.00 F	*560.00 F
<u>Supplementary #1</u>						
33	1		*COVER FRONT TOWING (WCP)	Missing	7.50 F	*7.50 F
34	1		*MESH FRONT RIGHT BUMPER CTR (WCP)	Distorted	115.00 F	*115.00 F

F=Franchise part.

Sub Total (\$)	11,232.50	7,817.50
+ Margin on L,N Items 10.00/10.00% (\$)	1,123.25	781.75
Total Parts (\$)	12,355.75	8,599.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	6	FENDER INNER SHIELD CLIP LH (NOT NECESSARY)	42.00	0.00
2	1	FRONT ENGINE COOLANT (NECESSARY)	25.00	25.00
3	6	FRONT RADIATOR TOP GARNISH CLIPS LH/RH (NECESSARY)	42.00	42.00
4	1	FRONT W/SCREEN SEALANT (NOT NECESSARY)	35.00	0.00
Sub Total (\$\$)			144.00	67.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER, SUPPORT PANEL , FENDER LH/RH, WHEEL HOUSE LH/RH CHASSIS LH/RH AND DAMAGE AREA	New	1,500.00	700.00
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION }	New	120.00	20.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS }	New	120.00	0.00
4	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA	New	350.00	60.00
5	TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00	250.00
6	TO REFILL A/COND GAS	New	80.00	80.00
7	TO CONDUCT 4 WHEEL ALIGNMENT	New	80.00	0.00
8	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND TENSIONER LH & RH , BUCKLE LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH	New	380.00	220.00
9	TO DISMANTLE & REFIX DASHBOARD , INCLUDING TO REMOVE & REPLACE PASSENGER SEAT AIR BAG AND DRIVER SEAT AIRBAG	New	480.00	250.00
10	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , FRONT BUMPER, SUPPORT PANEL , FRONT FENDER LH/RH WHEEL HOUSE LH/RH AND POLISH DAMAGE AREAS	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			4,690.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >